THE SEWERAGE AND WATER BOARD OF NEW ORLEANS

CARROLLTON WATER PLANT TURBINE GENERATOR 5 EXPLOSION INCIDENT December 14, 2019 CAUSAL ANALYSIS AND RECOMMENDATIONS FINAL REPORT

30 November 2020 PS-**4429639** Contract: 0001505

Submitted by:

ABS Group 1701 City Plaza Drive Spring, TX 77389





NOTICE

This work was performed by ABSG Consulting Inc. for the Sewerage and Water Board of New Orleans under proposal number 4429639; contract 0001505.

This report was prepared by ABSG Consulting Inc. solely for the benefit of the Sewerage and Water Board of New Orleans. Neither ABSG Consulting Inc., nor any person acting on their behalf, makes any warranty (express or implied) or assumes any liability to any third party with respect to the use of any information or methods disclosed in this report. Any third-party recipient of this report, by acceptance or use of this report, releases ABSG Consulting Inc. from liability for any direct, indirect, consequential, special loss or damage, whether arising in contract, tort (including negligence), or otherwise.

ABSG Consulting Inc. and its employees, subcontractors, consultants, and other assigns cannot, individually or collectively, predict what will happen in the future. The investigation team made a reasonable effort, based on the information and scope of work provided by personnel, to help identify mechanical and operational deficiencies that caused the Turbine Generator 5 explosion of December 14, 2019.

The Sewerage and Water Board of New Orleans should recognize that there may be other risks not addressed in this report. Regardless of what actions are taken in response to the information contained in this report, the potential exists for accidents and other abnormal events to occur. ABSG Consulting Inc. accepts no liability for any incident or regulatory action (international, federal, state, or local) that occurs with the Sewerage and Water Board of New Orleans power generating turbines, even if all the recommendations resulting from this incident investigation are thoroughly addressed.



EXECUTIVE SUMMARY

The Sewerage and Water Board of New Orleans (SWBNO) relies upon a set of five turbine generators to power water supply and storm water drainage pumps. On December 14, 2019 Turbine Generator 4 (TG 4) experienced a loss of steam pressure due a loss of compressed air in the boiler room resulting in TG 4 shutting down. It was necessary to bring Turbine Generator (TG) 5 online to replace the power generation that had been provided by TG 4. During startup of TG 5, an explosion occurred resulting in damage to parts of the TG 5 system, minor injuries to some SWBNO personnel, and limited damage to offsite structures.

ABSG Consulting Inc. (ABS Group) was contracted by SWBNO to conduct an investigation of the December 14, 2019 TG 5 explosion with the following objectives:

- Determine causal factors of the December 14, 2019 incident
- Develop recommendations to minimize potential for future occurrence

METHODOLOGY

The causal analysis investigated and analyzed the proximate causes (i.e., equipment and front-line personnel performance gaps, also referred to as causal factors) of the loss event; including their origin, relationship to other causal factors and how they collectively caused the loss event. This investigation scope did not include identification of root causes of each causal factor. Therefore, recommended corrective actions are offered to address identified causal factors only.

CAUSE AND EFFECT TREE

The December 14th TG 5 explosion was analyzed using a Cause and Effect Tree (CAET), which is a logicbased flow chart that describes potential combinations of conditions and events that contributed to the loss event. It indicates how the causal factors combined to cause the loss event. The CAET is useful for documenting the confirming and contradicting evidence for each potential causal factor and establishing the plausibility of each.

DEFINING THE LOSS EVENTS

For purposes of the investigation, a loss event is defined as an unplanned event or incident with consequences that are a deviation from a normal or optimal performance or outcome that might otherwise be expected under similar circumstances. The "loss event" for this investigation was an explosion that occurred during a startup attempt of TG 5 at approximately 13:47 hours on December 14, 2019. During the firing attempt, TG 5 exploded resulting in damage to the turbine. As of the writing of this report (30 November 2020) TG 5 remained out of service.



SCHEDULE

ABS Group prepared a preliminary list of data requested for the investigation and transmitted to SWBNO on February 21, 2020. Investigation milestones occurred on the following dates:

- December 22-23, 2019
 ABS Group incident scene orientation and investigation scoping at SWBNO
- March 20, 2020
 ABS Group receipt of assembled background information from
 - SWBNO
- April 14 May 05, 2020 Witness interviews
- May 26 May 27, 2020 Documentation of as-found conditions of equipment
- July 14 July 16, 2020 TG 5 Startup Simulation Testing
- August 25, 2020 Briefing of causal analysis results and recommendations

SPECIFIC CAUSAL FACTORS & RECOMMENDATIONS FOR CORRECTIVE ACTION

The causal factors of the loss event as identified based on a CAET analysis of the events is provided below.

Causal Factor 1:

The control air supply to the gas pressure ratio pilot valve (VPR-10) was 30 psi, 10 psi above the specified value of 20 psi +/- 0.5 psi.

Causal Factor 2:

The gas pressure ratio pilot valve fuel gas pressure offset at zero Compressor Discharge Pressure (CDP) was ~20 psi above specified value of 6 psi.

Causal Factor 3:

The gas pressure ratio pilot valve was slow to adjust to inputs and to command the gas pressure ratio (Leslie) valve to close.

Causal Factor 4:

The fuel gas supply ¼-turn shutoff valve may not have been opened until after the operation selector switch was set to auto (i.e., the valve may have been opened out of sequence).

Causal Factor 5:

The gas pressure ratio valve was slow to adjust to the pilot control signals to close.



CORRECTIVE ACTIONS TO ADDRESS LOSS EVENT CAUSAL FACTORS

The following are recommended procedural and operational changes that the Sewerage and Water Board of New Orleans should consider to address the causal factors identified for the December 14, 2019 TG 5 explosion.

Recommendation #1:

Set and maintain gas pressure ratio pilot valve control air to the correct value.

Causal Factors Addressed:

<u>Causal Factor 1</u>: The control air to the gas pressure ratio pilot valve (VPR-10) was set 10 psi above the specified value of 20 psi +/- 0.5 psi

Recommendation #2:

Develop and use management of change to control and maintain future changes to the control system.

Causal Factors Addressed:

<u>Causal Factor 1</u>: The control air to the gas pressure ratio pilot valve (VPR-10) was set 10 psi above the specified value of 20 psi +/- 0.5 psi

<u>Causal Factor 2</u>: The gas pressure ratio pilot valve zero fuel gas pressure offset was ~20 psi above specified value of 6 psi.

Recommendation #3:

Set and maintain gas pressure ratio pilot valve to proper zero CDP fuel gas pressure offset for operation of TG 5.

Causal Factors Addressed:

<u>Causal Factor 2</u>: The gas pressure ratio pilot valve zero fuel gas pressure offset was ~20 psi above specified value of 6 psi.

Recommendation #4:

Requalify both the gas pressure ratio valve and pilot to specified operation by a certified vendor.

Causal Factors Addressed:

<u>Causal Factor 3:</u> The gas pressure ratio pilot valve was slow to control the gas pressure ratio valve.

<u>Causal Factor 5:</u> The gas pressure ratio valve was slow to adjust to pilot control signal.



Recommendation #5:

Replace both the gas pressure ratio valve and pilot with a modern gas ratio valve and controller.

Causal Factors Addressed:

<u>Causal Factor 3:</u> The gas pressure ratio pilot valve was slow to control the gas pressure ratio valve.

<u>Causal Factor 5:</u> The gas pressure ratio valve was slow to adjust to pilot control signal.

Recommendation #6:

Add the following permissives to begin the startup sequence (e.g., to start the automatic startup sequence when the master control switch is turned to the start position).

- Fuel supply ¼-turn shutoff valve open
- No combustible gas in exhaust duct near combustion chamber prior to onset of firing

Causal Factors Addressed:

<u>Causal Factor 4</u>: The fuel gas supply ¼-turn shutoff valve may not have been opened until after Operation Selector Switch set to auto.

Recommendation #7:

Perform HAZOP of the TG 5 control system to identify and mitigate potential excessive fuel flows during the startup sequence.

Causal Factors Addressed:

<u>Causal Factor 4:</u> The fuel gas supply ¼-turn shutoff valve may not have been opened until after Operation Selector Switch set to auto.

Recommendation #8:

Add the following permissive to begin the startup sequence (e.g., to start the automatic startup sequence when the master control switch is turned to the start position).

• Gas pressure ratio valve closed

Causal Factors Addressed:

<u>Causal Factor 5:</u> The gas pressure ratio valve was slow to adjust to pilot control signal.



ТΔ	RI	F (JE	റവ	VTE	ΝΤς
			<u> </u>	COI		

	/E SUMMARY	3
TABLE OF	CONTENTS	7
LIST OF T	ABLES	8
LIST OF F	IGURES	8
1 INT	RODUCTION	
		10
1.1		10
1.2		10
1.5		11 11
1.4		11 12
1.5		12
1.0		17
1.7		
2 TUR	BINE GENERATOR 5 DESCRIPTION AND STARTUP PROCESS	
2.1	CONTROL SYSTEMS	21
2.1.	1 Electric Panel and relays	23
2.1.	2 Pneumatic Controls	24
2.1.	3 Fuel Control system	25
2.1.	4 Combusion System Components	25
3 DAT	A COLLECTION	
4 INC	IDENT DESCRIPTION	39
4.1	EVENTS PRIOR TO THE INCIDENT	44
4.1.	1 Maintenance Outages	11
4.1.	2 Pre-Incident TG 5 Operation and FINal Preventative Maintenance	
5 ANA	ALYSIS	44 47 49
5 ANA 5.1	ALYSIS PNEUMATIC CONTROLS	44 47 49
5 ANA 5.1 5.2	ALYSIS PNEUMATIC CONTROLS ELECTRICAL PANEL AND RELAYS	44 47 49 49 51
5 ANA 5.1 5.2 5.3	ALYSIS PNEUMATIC CONTROLS ELECTRICAL PANEL AND RELAYS SPARK PLUGS	44 47 49 51 51
5 ANA 5.1 5.2 5.3 5.4	ALYSIS PNEUMATIC CONTROLS ELECTRICAL PANEL AND RELAYS SPARK PLUGS TURBINE COMPRESSOR AIR INTAKE	
5 ANA 5.1 5.2 5.3 5.4 5.5	ALYSIS PNEUMATIC CONTROLS ELECTRICAL PANEL AND RELAYS SPARK PLUGS TURBINE COMPRESSOR AIR INTAKE FUEL GAS SYSTEM	
5 ANA 5.1 5.2 5.3 5.4 5.5 5.5	ALYSIS	
5 ANA 5.1 5.2 5.3 5.4 5.5 5.5. 5.5.	ALYSIS PNEUMATIC CONTROLS ELECTRICAL PANEL AND RELAYS SPARK PLUGS TURBINE COMPRESSOR AIR INTAKE FUEL GAS SYSTEM 1 Gas Pressure Ratio Valve and Pilot 2 Stop Valve	
5 ANA 5.1 5.2 5.3 5.4 5.5 5.5 5.5 5.5	ALYSIS PNEUMATIC CONTROLS ELECTRICAL PANEL AND RELAYS SPARK PLUGS TURBINE COMPRESSOR AIR INTAKE FUEL GAS SYSTEM 1 Gas Pressure Ratio Valve and Pilot 2 Stop Valve	
5 ANA 5.1 5.2 5.3 5.4 5.5 5.5 5.5 5.5 5.5 5.5	ALYSIS PNEUMATIC CONTROLS ELECTRICAL PANEL AND RELAYS SPARK PLUGS TURBINE COMPRESSOR AIR INTAKE FUEL GAS SYSTEM 1 Gas Pressure Ratio Valve and Pilot 2 Stop Valve 3 Gas Control Valve JSAL FACTORS AND RECOMMENDATIONS	
5 ANA 5.1 5.2 5.3 5.4 5.5 5.5 5.5 5.5 5.5 5.5 5.5 7 CAL 7 REF	ALYSIS PNEUMATIC CONTROLS ELECTRICAL PANEL AND RELAYS SPARK PLUGS TURBINE COMPRESSOR AIR INTAKE FUEL GAS SYSTEM 1 Gas Pressure Ratio Valve and Pilot	
5 ANA 5.1 5.2 5.3 5.4 5.5 5.5. 5.5. 5.5. 6 CAU 7 REF	ALYSIS PNEUMATIC CONTROLS ELECTRICAL PANEL AND RELAYS SPARK PLUGS TURBINE COMPRESSOR AIR INTAKE FUEL GAS SYSTEM 1 Gas Pressure Ratio Valve and Pilot 2 Stop Valve 3 Gas Control Valve 3 Gas Control Valve VSAL FACTORS AND RECOMMENDATIONS	
5 ANA 5.1 5.2 5.3 5.4 5.5 5.5. 5.5. 5.5. 6 CAU 7 REF APPENDI	ALYSIS PNEUMATIC CONTROLS ELECTRICAL PANEL AND RELAYS SPARK PLUGS TURBINE COMPRESSOR AIR INTAKE FUEL GAS SYSTEM 1 Gas Pressure Ratio Valve and Pilot 2 Stop Valve 3 Gas Control Valve JSAL FACTORS AND RECOMMENDATIONS ERENCES X A – TIMELINES X B – CAUSE AND EFFECT TREE	



Final Report

LIST OF TABLES

TABLE 1. SWBNO POWER GENERATION ASSETS	10
TABLE 2. INCIDENT INVESTIGATION TEAM	11
TABLE 3. TURBINE GENERATOR 5 COMBUSTION SCENARIO MATRIX (CAET BRANCHES)	17
TABLE 4. TURBINE GENERATOR 5 RELAY LAYOUT (SEE FIGURE 9 (B))	24
TABLE 5. TURBINE GENERATOR 5 DRY AIR VPRS	24
TABLE 6. SUMMARY OF SWBNO PERSONNEL INTERVIEWED BY ABS GROUP	38
TABLE 7. TIMELINE OF EVENTS RELATED TO TG 5 STARTUP DECEMBER 14 FROM SECURITY FOOTAGE	41
TABLE 8. SUMMARY OF TURBINE GENERATOR 5 MAINTENANCE	45
TABLE 9. START-UP SIMULATION TESTS	49
TABLE 10. TURBINE GENERATOR 5 DRY AIR VPRS	50
TABLE 11. GAS PRESSURE RATIO VALVE CLOSE TEST AFTER ESTABLISHING FUEL GAS PRESSURE	62
TABLE 12. TEST CASE SCENARIOS	64
TABLE 13. FUEL GAS STOP VALVE LEAK TEST RESULTS	70
TABLE 14. CAUSAL FACTORS AND RECOMMENDATIONS	73

LIST OF FIGURES

FIGURE 1. CAET PLAUSIBILITY	12
FIGURE 2. TOP LEVEL CAUSE AND EFFECT TREE	14
FIGURE 3. INTERMEDIATE LEVEL CAUSE AND EFFECT TREE	15
FIGURE 4. DETAILED LEVEL CAUSE AND EFFECT TREE (PARTIAL)	16
FIGURE 5. TURBINE GENERATOR 5 CUTAWAY AND SCHEMATIC GAS FLOW DIAGRAMS	
FIGURE 6. TURBINE GENERATOR 5 SWBNO AUTOMATIC START-UP SEQUENCE	20
FIGURE 7. TURBINE GENERATOR 5 CONTROL SYSTEM SCHEMATIC DIAGRAM	21
FIGURE 8. CONTROL PLATE AND LINKAGES	22
FIGURE 9. TURBINE GENERATOR 5 CONTROL PANEL (A) AND RELAYS (B)	23
FIGURE 10. TURBINE GENERATOR 5 CONTROL CABINET	25
FIGURE 11. CARROLLTON WATER PLANT HIGH AND LOW LIFT PUMP BUILDINGS	26
FIGURE 12. TURBINE GENERATOR 5 COMPRESSOR AIR INTAKE ELEVATION	27
FIGURE 13. TURBINE GENERATOR 5 COMPRESSOR EXHAUST DUCTING ELEVATION	28
FIGURE 14. TURBINE GENERATOR 5 COMBUSTION CHAMBER ARRANGEMENT	29
FIGURE 15. SPARK PLUG CROSS-SECTION	30
FIGURE 16. TURBINE GENERATOR 5 SPARK PLUGS	30
FIGURE 17. TURBINE GENERATOR 5 FLAME DETECTORS	31
FIGURE 18. FLAME DETECTOR TROUBLE LIGHTS (TOP ROW)	31
FIGURE 19. FUEL GAS AND FUEL GAS NOZZLE PURGING PIPING DIAGRAM	33
FIGURE 20. FUEL GAS EXTERIOR ISOLATION VALVE (CLOSED POSITION)	34
FIGURE 21. FUEL GAS STRAINER	34
FIGURE 22. FUEL GAS ¼-TURN MANUAL ISOLATION VALVE (CLOSED POSITION)	35
FIGURE 23. FUEL GAS PRESSURE RATIO VALVE (OPEN POSITION) AND PILOT (GREY)	35
FIGURE 24. FUEL GAS STOP VALVE (CLOSED POSITION)	36
FIGURE 25. FUEL GAS CONTROL VALVE (CLOSED POSITION)	36
FIGURE 26. TURBINE GENERATOR 5 EXPLOSION DECEMBER 14, 2019 14:37:30	
FIGURE 27. TURBINE GENERATOR 5 EXPLOSION EXHAUST STACK FIREBALL	
FIGURE 28. PHOTOGRAPH OF CENTRAL CONTROL LOG REMARKS FROM DECEMBER 14, 2019	42
FIGURE 29. APPROXIMATE TIME OF EXPLOSION DURING THE START-UP SEQUENCE	43



FIGURE 30. SWBNO DECEMBER 12 TURBINE GENERATOR 5 MAINTENANCE TICKET AND TRACKING REPORT	47
FIGURE 31. TURBINE GENERATOR 5 DECEMBER 12, 2019 TEST RUN LOG SHEET	48
FIGURE 32. VPR-10 SPECIFIED VALVE SETTINGS	50
FIGURE 33. VPR-10, GAS PRESSURE RATIO PILOT VALVE CONTROL AIR SUPPLY, - AS-FOUND PRESSURE	51
FIGURE 34. TURBINE GENERATOR 5 IGNITORS DURING TEST SIMULATION	51
FIGURE 35. COMPRESSOR AIR INTAKE SCREEN AND DUCTING	52
FIGURE 36. CAET EXCESS FUEL GAS FLOW MAJOR BRANCHES	54
FIGURE 37. TURBINE GENERATOR 5 GAS PRESSURE RATIO VALVE AND PILOT	55
FIGURE 38. GAS PRESSURE RATIO PILOT VALVE SPECIFIED ZERO CDP OFFSET AND PRESSURE RATIO	56
FIGURE 39. GE OUTAGE REPORT PRESSURE RATIO PILOT VALVE CONDITION DESCRIPTION	57
FIGURE 40. GE TURBINE STARTUP RECORD	58
FIGURE 41. GE TURBINE OPERATION READINGS	59
FIGURE 42. GAS PRESSURE RATIO PILOT VALVE CDP VS DOWNSTREAM FUEL GAS PRESSURE P2	61
FIGURE 43. GAS PRESSURE RATIO VALVE POSITION VS TIME AFTER ESTABLISHING FUEL GAS PRESSURE	63
FIGURE 44. AUTOMATIC START UP AND TEST SCENARIO – ESTABLISHMENT OF FUEL GAS PRESSURE	65
FIGURE 45. TEST SCENARIO 1 - GAS PRESSURE RATIO VALVE POSITION AND PILOT OUTPUT PRESSURE	66
FIGURE 46. TEST SCENARIO 2 - GAS PRESSURE RATIO VALVE POSITION AND PILOT OUTPUT PRESSURE	67
FIGURE 47. GAS PRESSURE RATIO VALVE PILOT DRAWING FROM GEI-40960	68
FIGURE 48. TEST SCENARIOS - GAS PRESSURE RATIO VALVE TRAVEL VS PERCENTAGE OF FUEL GAS FLOW	69
FIGURE 49. FUEL GAS STOP VALVE OPERATION DURING START-UP SIMULATION	70
FIGURE 50. FUEL GAS PRESSURE BEFORE THE STOP VALVE DURING LEAK TESTING	71
FIGURE 51. GAS CONTROL VALVE POSITION DURING STARTUP SIMULATION	72



1 INTRODUCTION

The Sewerage and Water Board of New Orleans (SWBNO) relies upon a set of five turbine generators to power water supply and storm water drainage pumps. A summary of the SWBNO power generation turbines is provided in Table 1^[1]. On December 14, 2019, Turbine Generator (TG) 4 experienced a loss of steam due to loss of compressed air from the boiler room resulting in TG 4 shutting down. It was necessary to bring TG 5 online to replace the power generation that was being provided by TG 4. During startup of TG 5, an explosion occurred resulting in damage to the TG 5, injuries to the operators in the vicinity of the turbine, and damage to nearby community residential structures.

Turbine	ТҮРЕ	Year	Frequency (Hz)	Power Rating, megawatts (MW)
Turbine Generator 1	Steam turbine	1909	25	6
Turbine Generator 3	Steam turbine	1929	25	15
Turbine Generator 4	Steam turbine	1915 ¹	25	20
Turbine Generator 5	Dual fuel turbine	1958 ²	25	20
Turking Constant	Duel fuel turking	1001	60	20
Turbine Generator 6	Duai ruel turbine	1981	25	6

Table 1. SWBNO Power Generation Assets

¹ Refurbished 2017

² Forced Outages 2017 and 2019

ABS Group was contracted by SWBNO to determine the causal factors of the TG 5 explosion that occurred during startup of the turbine on December 14, 2019 and to develop recommendations based upon the causal factors to minimize the potential for future recurrence.

1.1 THE LOSS EVENT

On December 14, 2019 at approximately 13:47 hours, an explosion during startup of TG 5 occurred during the first firing attempt at the SWBNO Carrollton Water Plant resulting in damage to parts of the turbine. As of the delivery of this report (30 November, 2020) TG 5 remained out of service.

1.2 THE INVESTIGATION TEAM

An investigation team was organized that included personnel from ABS Group and SWBNO. The ABS Group investigation team members and the SWBNO investigation project manager are identified in Table 2.

¹ Sewerage & Water Board System Overview Presentation, January 2018.

² Sewerage & Water Board Power Generation and Drainage System FAQs, 14 August 2017.



Final Report Table 2. Incident Investigation Team

Name	Organization	Title	
Ben Harrison, P.E.	ABS Group	Lead Investigator	
Charles Vergara	ABS Group	Supporting Investigator	
Lee Vandenheuvel	ABS Group	Investigations Manager	
Darroll Parker, D.E.	APS Group	Project Manager	
	Abs Gloup	Customer Service Representative	
Tommy Moore	SWBNO	SWBNO Project Manager	

1.3 INVESTIGATION AND DATA COLLECTION

ABS Group personnel met with SWBNO personnel at the Carrollton Water Plant in New Orleans on December 22, 2019, eight days after the December 14 incident, to establish the scope of the investigation and to gain a fundamental understanding of the events leading up to the incident. On March 2, 2020, ABS Group received notice from SWBNO to proceed with the following activities:

- Determine causal factors of the December 14, 2019 incident
- Develop recommendations to minimize potential for future occurrence

Investigation milestones occurred on the following dates:

- March 20, 2020 Receipt of assembled background information from SWBNO
- April 14 May 05, 2020 Witness interviews (performed remotely)
- May 26 May 27, 2020 Documentation of as-found conditions of equipment (onsite)
- July 14 July 16, 2020 TG 5 Startup Simulation Testing (onsite)
- August 25, 2020 Briefing of causal analysis results and recommendations (remotely)

ABS Group interviewed eleven SWBNO personnel six from Operations, one from the Mechanical Shop, three from the Electrical Shop, and one from the Instrument Shop. Operations interviews included the operator starting TG 5 on the date of the incident, the supporting operators who were shutting down TG 4 on the date of the incident, and the operator who started the TG 5 successfully on December 12th (the last successful startup of TG 5 prior to the incident).

1.4 METHODOLOGY

The causal analysis investigated and identified the failures (i.e., equipment performance gaps and frontline personnel performance gaps) contributing to the explosion of TG 5 on December 14, 2019 (the loss event). These performance gaps are referred to as causal factors (CF). Once these causal factors are identified, factors contributing the performance gaps are developed through analysis of the data and interviews with personnel. These contributing factors are often referred to as intermediate causes and typically include performance gaps in design, maintenance, documentation, materials/parts, hazard/defect identification, procedures, human factors, training, supervision, communication, personnel performance, and external factors. The investigation team used ABS Group's proven



SOURCE[™] (Seeking Out the Underlying Root Causes of Events) methodology for the causal analysis^[3]. Root cause determination was not part of the scope of this effort, but the underlying methodology is similar.

1.5 CAUSE AND EFFECT TREE

One analysis technique used for evaluation of the TG 5 explosion was a Cause and Effect Tree (CAET). This technique lays out the causal and intermediate factors on a logic tree that describes potential combinations of conditions and events that contributed to the loss event. The branches in the CAET are colored-coded based upon the plausibility of the event. Plausibility is the likelihood that the postulated event occurred and contributed to the incident. Red events are very highly plausible, and green are very low as shown in Figure 1. Plausibility is based upon:

- Confirming Data supports the occurrence and contribution of the potential cause pushes towards red
- Contradicting Data refutes the occurrence and contribution of the potential cause pushes towards green



Figure 1. CAET Plausibility

Causes are tied to effect(s) through AND gates and OR gates. AND gates are utilized whenever a combination of events is required to cause the effect that is above the AND gate. The effect carries the lowest plausibility of the connected causes because all of the connected causes are required to occur to create the effect. OR gates are utilized whenever any one of the possible causes may result in the effect above the gate; therefore, the effect shows the highest plausibility of any of the potential causes since any single cause may result in the effect.

³ Vanden Heuvel, Lee et al., "Root Cause Analysis Handbook", ABS Consulting, Rothstein Associates Inc Publishers, 2008.



The top of the CAET for this loss event is shown in Figure 2. The box colors indicate the plausibility of the event listed in the box occurred and contributed to the loss event. The detailed CAET considered a wide range of potential contributing events, including equipment failures and personnel performance failures. An intermediate level CAET is shown in Figure 3 and a detail level in Figure 4. The complete detailed CAET provided in larger format is included in Appendix B.

Final Report

ABS Group

30 November 2020



Figure 2. Top Level Cause and Effect Tree





Figure 3. Intermediate Level Cause and Effect Tree



Final Report



Figure 4. Detailed Level Cause and Effect Tree (Partial)



1.6 TIMELINES

The second technique used in the causal analysis is an event timeline. The timeline establishes the temporal relationships of equipment and personnel and is important to understand the causes for the explosion. A detailed timeline is provided in Appendix A.

1.7 ANALYSIS

The project team used the data collected to confirm or contradict each of the potential causes developed in the CAET. Analyses were conducted principally in the following areas:

- TG 5 Controls
- TG 5 Operation
- TG 5 Combustion
- Combustion Air
- Combustion Fuel Gas
- Ignition

A matrix of combustion abnormalities was created to summarize the evaluation of combination scenarios as depicted in Table 3 for igniter behavior and fuel gas flow.

		Gas Flow			
		Unintended Fuel Gas			
Spark Plug Behavior	Normal	Flow	Excess Fuel Gas Flow		
Normal Ignition	Not Evaluated	2.1.1/2.2	2.1.2/2.2		
No Ignition	1.2.1	Not Evaluated	Not Evaluated		
Ignition Too Soon	1.2.2	Not Evaluated	Not Evaluated		
Ignition Too Late	1.2.3	Not Evaluated	Not Evaluated		
Ignition Energy Too	1.2.4	Not Evaluated	Not Evaluated		
Low					

Table 3. Turbine Generator 5 Combustion Scenario Matrix (CAET Branches)

An evaluation of each of these topics is provided in Section 5. Data and results of the analysis is included in the appendices.



2 TURBINE GENERATOR 5 DESCRIPTION AND STARTUP PROCESS

Turbine Generator 5, Serial No 127724, was approved for construction in 1959 and in 1960 General Electric (GE) published instruction GEI-40960^[4], which contains the instructions and recommended procedures for the operation, service, and maintenance of the turbine. GEI-40960 describes TG 5 as an open simple-cycle, one-shaft design with in-line arrangement of its components. The unit consists of three basic components; the axial-flow compressor, the combustion chambers, and the turbine, as depicted in Figure 5, which is connected to generator serial number 8300411.

The gas turbine-generator is started by a cranking motor. When the cranking motor gets the unit up to approximately 20% speed (750 rpm), the turbine initiates a purge sequence and then spark plugs are initiated and fuel is introduced into the combustion chamber where the spark plugs ignite the fuel/air mixture. The cranking motor assists the turbine up to 50% to 60% of rated speed at which time the cranking motor clutch is disengaged. The unit then accelerates to operating speed on governor control and is available for loading.



Figure 5. Turbine Generator 5 Cutaway and Schematic Gas Flow Diagrams

⁴ GEI-40960, "Gas Turbine-Generator Unit 20,200 KW Gas Turbine No. 127724, Generator NO. 8300411", Sewerage and Water Board of New Orleans Purchaser's Order NO 198-W, Gas Turbine Department General Electric, Schenectady, N.Y., 1960.



The startup sequence and operation of control relays is described in GEI-77036A^[5], (starting on page 535 of GEI-40960). The start-up sequence in GEI-77036A is not enumerated here; however, the SWBNO Automatic Start-Up sequence diagram, SWNO DWG No 10948-W-2 is provided in Figure 6. The SWBNO startup sequence is dated July 8, 1963 and was produced three years after GEI-77036A^[6].

⁵ GEI-77036A, "Gas Turbine Generator 20,200 KW", Medium Voltage Switchgear Department, General Electric, Philadelphia, PA, August 1960.

⁶ Sewerage and Water Board of N.O. DWG No. 10948-W-2, "Sewerage & Water Board Gas Turbine Start-Up Sequence", July 8, 1963.



ABS Group

30 November 2020



Figure 6. Turbine Generator 5 SWBNO Automatic Start-Up Sequence



2.1 CONTROL SYSTEMS

GEI-40960^[4] describes the turbine control system as a mechanical hydraulic control to regulate the speed and load of the unit by controlling the amount of fuel fed to the combustion chambers. The control components, shown in Figure 7, may be described as consisting of the following four basic systems:

- Speed Control System
- Temperature Control System
- Fuel Control System
- Emergency Trip and Protection System



Figure 7. Turbine Generator 5 Control System Schematic Diagram

The starting and fuel limit control is physically part of the fuel control mechanism. Per GEI-40960^[4] the starting of the gas turbine is accomplished by means of the minimum fuel relays, the synchronizing device, or speed changer, and the primary relay from signals in the electric control panel.

The primary relay is a hydraulically operated device which amplifies the power of the centrifugal speed governor and integrates their motion through the levers and linkages, shown below in Figure 8, to give the required position signals to the gas control valve.





Figure 8. Control Plate and Linkages



2.1.1 ELECTRIC PANEL AND RELAYS

TG 5 control panel is shown below in Figure 9. The control panel incorporates the various switches, relays, timers and other devices which set up the control sequence for starting, accelerating, and running the turbine. The switches and annunciator panel are shown in Figure 9 (a) and the relays and timers in Figure 9 (b). Table 4 provides the layout of the relays and timers.





Figure 9. Turbine Generator 5 Control Panel (a) and Relays (b)



Table 4. Turbine Generator 5 Relay Layout (see Figure 9 (b))

4-1	1	4-2	
4Y	14HMX-1	14HMX-2	2ΤVΥ
2FY	95FDX	95FDZ	95FDY
14HSX-1	14HSX-2	3	94
84TLX	84TGX	83FX	63FG-IX
2WX			RPM Indicator
2TV	2F	2W	2FT

2.1.2 PNEUMATIC CONTROLS

Control air is regulated by pressure reducing valves (VPRs), as identified in Table 5. Control air for the temperature control system is in the TG 5 Control Cabinet shown below in Figure 10.

Name	from	to	P&ID - Sheet	Specified Setting
VPR-2	Referenced on P&ID (916B455-Sheet 7)		916B455-Sheet 7	85 psig
VPR-3	Air Supply	TEMR transmitter	916B455-Sheet 5	20 psig
VPR-4	Air Supply	Butterfly control valve	916B455-Sheet 5	20 psig
VPR-5	Air Supply	Pneumatic Controller	916B455-Sheet 5	20 psig
VPR-6	Air Supply	Pneumatic Controller	916B455-Sheet 5	See Cont. Specs.
VPR-7	7 Within the pneumatic temperature relay		916B455-Sheet 4	32 psig,⁺/₋ 0.5 psi
VPR-8	Air Supply	OT trip	916B455-Sheet 4	62 psig,⁺/₋ 0.5 psi
VPR-9	Air Supply	Fuel Gas Control Valve	916B455-Sheet 6	35 psig,⁺/₋ 0.5 psi
VPR-10	Air Supply	Gas pressure ratio pilot valve	916B455-Sheet 6	20 psig,⁺/₋ 0.5 psi

Table 5. Turbine Generator 5 Dry Air VPRs



Final Report



Figure 10. Turbine Generator 5 Control Cabinet

2.1.3 FUEL CONTROL SYSTEM

The fuel control system supplies fuel to the combustion chambers during operation of the turbine after startup in response to turbine speed and turbine temperature based on signals from the speed control system and the temperature control system. During startup of the turbine, the speed changer positions the primary relay directly below the lowest governing speed of the turbine and provides the accelerating fuel strokes require to bring the turbine to the lowest governing speed after startup^[4]. This is indicated by the startup position of the fuel gas control valve as set by the primary relay.

The fuel gas is primarily controlled during the turbine ignition by the gas pressure ratio valve (the Leslie valve) and its pilot valve.

2.1.4 COMBUSION SYSTEM COMPONENTS

2.1.4.1 COMPRESSOR AIR INTAKE AND EXHAUST SYSTEM

The Carrollton Water Plant High and Low Lift buildings where TG 5 are located is shown in Figure 11. Eagle Street is located to plant west and Spruce St. to plant south of the building. The air intake is located to plant south of the High Lift Pump Building and compressor intake air is drawn in and ducted into the turbine from the underside as shown in the elevation of the intake ducting in Figure 12. The compressor exhaust is ducted from underneath the outlet of the turbine to plant east to the tall vertical stack as indicated in the turbine compressor exhaust elevation in Figure 13.





Figure 11. Carrollton Water Plant High and Low Lift Pump Buildings





Figure 12. Turbine Generator 5 Compressor Air Intake Elevation





Figure 13. Turbine Generator 5 Compressor Exhaust Ducting Elevation



2.1.4.2 SPARK PLUGS AND FLAME DETECTION

TG 5 has sixteen combustion chambers that are arranged as shown in Figure 14 and are numbered sequentially, counter clockwise (facing downstream) from the twelve o'clock position^[4]. Two spark plugs are provided for ignition of the turbine and they are both located on the left hand side as shown in Figure 14. They are in combustion chambers 4 and 5 which are located just above and below the 9 o'clock position. The spark plug position in combustion chambers 4 and 5 is shown in section B-B of Figure 14. The spark plug cross-section is shown in Figure 15 and the spark plugs are shown in position on TG 5 in Figure 16.



Figure 14. Turbine Generator 5 Combustion Chamber Arrangement



Final Report



Figure 15. Spark Plug Cross-Section



Figure 16. Turbine Generator 5 Spark Plugs

Flame detectors are located on the opposite side of TG 5 from the spark plugs. The flame detectors are located on the right side of the turbine, or the three o'clock position, when looking in the direction of flow and they are indicated in Figure 14 and shown on the turbine in Figure 17. The associated flame detection lights on the control panel are shown below in Figure 18. The flame detector numbers on the



Final Report

control panel refer to the combustion chamber numbers in Figure 14 where the flame detectors are located.



Figure 17. Turbine Generator 5 Flame Detectors



Figure 18. Flame Detector Trouble Lights (top row)



2.1.4.3 FUEL GAS SYSTEM

The fuel gas system, detailed in the Figure 19 piping diagram^[7], consists of:

- Fuel gas isolation valve outside of the building (Figure 20)
- Strainer (Figure 21)
- ¼-turn shutoff valve (Figure 22)
- Gas pressure ratio valve and pilot (Figure 23)
- Stop valve (Figure 24)
- Gas control valve (Figure 25)

The fuel gas line is a 4-inch line operating at approximately 200 psi. The fuel gas is strained and then piped to the turbine where it is kept isolated by the ¼-turn shutoff valve in Figure 22 when the turbine is not in operation. Just prior to startup the ¼-turn shutoff valve is opened to provide fuel gas up to the stop valve in Figure 24, which remains closed until Step C (timer 2F) of the firing sequences shown in Figure 6. The gas pressure ratio valve and associated pilot in Figure 23 control the fuel gas pressure before the stop valve during start-up and acceleration of the turbine when the governor, control linkages and fuel gas control valve, in Figure 25, take over regulation of the turbine speed.

⁷ GE Schematic Piping Diagrams, 916B455, July 15, 1959.



Final Report



Figure 19. Fuel Gas and Fuel Gas Nozzle Purging Piping Diagram





Figure 20. Fuel Gas Exterior Isolation Valve (Closed Position)



Figure 21. Fuel Gas Strainer





Figure 22. Fuel Gas ¼-Turn Manual Isolation Valve (Closed Position)



Figure 23. Fuel Gas Pressure Ratio Valve (Open Position) and Pilot (Grey)





Figure 24. Fuel Gas Stop Valve (Closed Position)



Figure 25. Fuel Gas Control Valve (Closed Position)


3 DATA COLLECTION

The analysis of the December 14, 2019 explosion incident required an extensive amount of data gathering. ABS Group was provided an information package from SWBNO on March 20, 2020 containing:

- Folder 1 Pre-Event Information
 - Folder 1.1 GE Outage Report and GE Timesheets
 - Folder 1.2 Empty / No Content
 - Folder 1.3 Document with Leslie Diaphragm Replacement CASS Record
 - Folder 1.4 CASS Work Tickets
 - Folder 1.5 SWB internal Outage Report and GE Operating Data and Troubleshooting Summary
 - Folder 1.6 GE SBWNO Forced Outage 2017 Report
- Folder 2 Contractual Information
 - Folder 2.2 SWBNO Agreements Since 2017
- Folder 3 Event Information (Videos and Interviews)
 - Folder 3.1 Post incident interviews by SWBNO Security
 - Folder 3.2 Post incident photos by SWBNO Security
 - Folder 3.3 Surveillance System Videos⁸
- Folder 4 Engine & Control Data Turbine 5
 - o GEI-40960 Gas Turbine-Generator Unit 20,200 KW No 127724
 - Cross-Section Diagram of the Gas Turbine
 - o Turbine Drawings (mechanical and electrical)
 - SWBNO DWG. No 10948-W-2 SWBNO Gas Turbine Automatic Start-Up Sequence
- Folder 5 Scope of Damages Turbine 5
 - Folder 5.1 Asbestos Abatement Report
 - Folder 5.2 Drawings of Exhaust Stack
 - Folder 5.4 Structural Evaluation Report
- Folder 6 GE Turnover Reports, GE Daily reports Feb 2019 through April 12, 2019

Several videos from various surveillance cameras on the site were provided to ABS Group. The surveillance video file of TG 5 from within the High Lift contained 5 seconds of pre-explosion footage and approximately 75 seconds of post-incident footage.

In addition to the information provided by SWBNO, ABS Group submitted six additional requests for information. Appendix C contains a summary of the status of the RFIs.

ABS Group interviewed eleven SWBNO personnel: six from Operations, one from the Mechanical Shop, three from the Electrical Shop, and one from the Instrument Shop as indicated in Table 6. Operations interviews included the operator starting the turbine on the date of the incident, Operator 1, the supporting operators who were busy shutting down TG 4 on the date of the incident, Operators 2 and 3,

⁸ Sewerage and Water Board of New Orleans, Carrollton Water Plant security camera footage, December 14, 2019.



and Operator 4 who started the turbine successfully on December 12th, the last successful startup of TG 5 prior to the incident.

Individual	Department	Title	Role	Date of Interview
Electrician 1	Electrical Maintenance	Utility Maintenance Supervisor	Electrical shop	14-Apr-20
Electrician 2	Electrical Maintenance	Utilities Maintenance Specialist I	Electrical shop	28-Apr-20
Electrician 3	Electrical Maintenance	Utilities Maintenance Specialist I	Electrical shop	28-Apr-20
Instrumentation 1	Instrument	Utilities Maintenance Supervisor	Low voltage systems	5-May-20
Maintenance 1	Mechanical Maintenance	Utilities Maintenances Specialist II	Supported maintenance work during outage	14-Apr-20
Operator 1	Operations	Supervisor III	Operator 1 - Startup December 14	5-May-20 27-May-20
Operator 2	Operations	P.P.O 4th Watch	Assisted Operator 1 – Startup December 14	15-Apr-20
Operator 3	Operations	U.P.W 1st Watch	Assisted Operator 1 – Startup December 14	15-Apr-20
Operator 4	Operations	S.P.E. II	Operator - Startup December 12	27-May-20
Operator 5	Operations	Supervisor IV		16-Apr-20
Operator 6	Operations	Supervisor III	Arrived Shortly After Incident	16-Apr-20

Table 6. Summary of SWBNO Personnel Interviewed by ABS Group

ABS Group visited the SWBNO Carrollton Water Plant on May 26 - 27, 2020 to document the as-found condition of TG 5 and a second visit was conducted from July 14 - 16, 2020 to conduct simulated testing of the TG 5 fuel gas system and start-up sequence.



4 INCIDENT DESCRIPTION

On December 14, 2019 at approximately 13:47 hours, an explosion during the startup attempt of TG 5 occurred at the SWBNO's Carrollton Water Plant. During the first firing attempt, TG 5 exploded resulting in the damage to the turbine, injuries to the operators in the vicinity of the turbine, and damage to nearby community residential structures as a result of the incident. As of the writing of this report TG 5 remained out of service. The fireball emanating from TG 5 casing is shown in Figure 26 and the fireball emanating from the exhaust stack is shown in Figure 27.



Figure 26. Turbine Generator 5 Explosion December 14, 2019 14:37:30



Figure 27. Turbine Generator 5 Explosion Exhaust Stack Fireball



On the day of the incident Operator 3 noticed that the shell temperature on TG 4 was high during his 13:00 round. Operator 2 called the Boiler Room and was notified that the Boiler Room was losing steam pressure and Operator 2 mentioned that approximately 5 minutes later, TG 4 went down due to loss of steam pressure. After the loss of TG 4, Central Control was notified and then Operators 2 and 3 called their supervisor, Operator 1, and requested that Operator 1 come to the Carrollton Water Plant to assist. Operator 1 was not on duty and was offsite at the time. Operator 2 stated that when Operator 1 arrived at the Carrolton Water Plant High Lift they called Central Control to inform them that the Boiler Room did not have steam to restart TG 4 and Central Control instructed the operators to start TG 5. Operator 2 started the following systems on TG 5: vapor extractor, lube oil, cooling water and Operator 3 started the circulating pumps. Operators 2 and 3 could not provide details regarding subsequent startup of TG 5, they both stated they were busy securing TG 4 at the time. Operator 1 indicated that during the start-up on December 14th the ¼ turn shutoff valve was opened just prior to notifying Central Control the turbine was ready to start. Operators 2 and 3 had the unit on turning gear when Operator 1 arrived. Operator 1 needed to toggle the air and reset the trips prior to being ready to start. Operator 1 stated that the ¼ turn shutoff valve is not opened until just after calling Central and starting the turbine and that after switching the turbine to start everything was coming up normally and there were no abnormal sounds. Once the cranking motor got to speed (~750 rpm as indicated in Figure 6), Operator 1 said the purge timer engaged and then the firing sequence began after completion of the purge. After 10 to 15 seconds, he noticed that the turbine should have fired and he thought something was wrong and went inside of the Accessory Gear Box to take a look at the gas pressure ratio valve. He "could hear and feel a rush of gas" which prompted Operator 1 to leave the room immediately out of concern. After leaving the Accessory Gear Box Operator 1 then waited for the turbine to go through the second purge prior to a second firing attempt; however, he stated that about 20 seconds after leaving the Accessory Gear Box Room the explosion occurred. The approximate time of the explosion was near the end of the first firing sequence as indicated on the start-up sequence plot in Figure 29. A timeline of Operator 1 activity as indicated by SWBNO surveillance camera on December 14, 2019. An abbreviated timeline summarizing these events is provided below in Table 7 and a detailed timeline is provided in Appendix Α.

A copy of the Central Control log remarks from December 14, 2019 are provided in Figure 28. The log remarks state that TG 5 was rolled for start-up at 13:38 and the explosion was logged at 13:45. Although the log entry states 13:38 as the time of TG 5 roll, video footage of both Boiler Control and Central Control are consistent with a final call to start the turbine at 13:42, approximately 5 ½ minutes prior to the TG 5 explosion at 13:47:30. The explosion log entry was made (as indicated by the Central Control video) at 13:56 and incorrectly noted the time of the incident as 13:45 rather than 13:47:30 as indicated by numerous security videos.



Table 7. Timeline of Events Related to TG 5 Startup December 14 from Security Footage

Local Time	Incident Time	Activity	Interpretation
13:35:55	(T – 11 min. 35 sec.)	Operator 1 arrives at main	Operator 1 travels to Low
		security gate	Lift Building and parks
13:36:10	(T – 11 min. 20 sec.)	Operator 1 traveling by vehicle	vehicle
		on plant.	Operator 1 walks through
13:38:05	(T – 9 min. 25 sec.)	Central and Boiler Control both	Low Lift to the High Lift and
		on the phone. Call lasts ~50 sec.	meets with Operator 2
		Central Control log entry made	and/or Operator 3 to get
		"Rolling #5 Turbine".	status of TG 4 and TG 5.
13:39:08	(T – 8 min. 22 sec.)	Central and Boiler Control both	Call to Central Control
		on the phone. Call lasts ~15 sec.	concerning boiler status.
13:42:03	(T – 5 min. 27 sec.)	Central and Boiler Control both	
		on the phone. Call lasts ~10 sec.	
			Probable time of TG 5 start.
		Last call both receive before the	
		incident.	
13:42:54	(T- 4 min. 36 sec.)	Operator 1 enters High Lift	
		Office and makes a call from the	
		fixed phone on the wall.	
13:43:18	(T – 4 min. 12 sec.)	Operator 1 exits the High Lift	TG 5 accelerating on turning
		Office.	gear.
13:44:25	(T – 3 min. 05 sec.)	Operator 1 enters High Lift	
		Office to make a call from a cell	
		phone	
13:44:45	(T- 2 min. 45 sec.)	Operator 2 or 3 (A second	
		Operator) enters the High Lift	TC E boginning first purgo
		Office	sequence
13:46:00	(T - 1 min. 30 sec.)	Operator 1 exits the High Lift	sequence.
		Office	
13:47:30	(T – 0 min. 0 sec.)	TG 5 explosion.	TG 5 at end of first firing
			sequence.

SEWERAGE AND WATER BOARD OF NEW ORLEANS CAUSAL ANALYSIS AND RECOMMENDATIONS



Final Report

	7140	DEWARKS	TIME	REMARKS
TIME REMARKS	HAL	in control to		
from Lost = U turbine				
for Re-englanze at comprostan 506 for 8910				
Un Kolling # Starbme				
12 Da. 6 25 power restart				
12pm Lost air pressure can't roll #5 turbin				
Denald (14C)				
12m Rolling & Sturbine				
In An explosion happened on is twitte				
324/Pm C.C. requested SHA.D to Start #44C				
35/pm C.C. reenergized KVA via Trans-3			1	
470/PM Dipiter (operator) Can not get DC UT-1 to close				
- estra. 1' requesting a electrician c.c. Notified & Mancuso				
441/PM (HL) starting #1 Circulating pimp			1	
504pm Shane (PSP) Rolling #1 thome			1	
5ª/en #1 turbure up to speed (HL)			1	
531/pm Making feild ON #1 whe - Not successful			1	
540/pm Having trouble raining of exciter theostar nonified H. Dinkel			-	
55/pm STOP #1 Turbing			-	
1.18/Pm Sam Lewis (P\$P) colling #1 twisine				
644/en CI turbine up to speed (PJP)				
SIPPIN Remelleling of W/ #3FC @ STA.D				
15/2 Notified H. Con run 25- simpling			-	
153/0 home will have be notice to normal remation				
ASA/C CC CLANNEL STOLD TO STUR #3+ #4FC'S				
and Curp minued & for Sime - Biller man and				
John Cup received a do suge such tost				
- Claborne stangus are okay				
			1	

Figure 28. Photograph of Central Control Log Remarks from December 14, 2019

SEWERAGE AND WATER BOARD OF NEW ORLEANS CAUSAL ANALYSIS AND RECOMMENDATIONS

Final Report

ABS Group

30 November 2020



Figure 29. Approximate Time of Explosion During the Start-up Sequence



4.1 EVENTS PRIOR TO THE INCIDENT

Prior to the incident of December 14, 2019 TG 5 had undergone a maintenance outage in 2017^[9] and a second outage in 2019^{[10],[11]}. The TG 5 outage in early 2019 consisted of three phases to complete the maintenance and troubleshooting, there was then an extensive operational run from October to December of 2019, and finally preventative maintenance and a test run on December 12th. These events are presented in the Timeline in Appendix A and the key points summarized in the following sections.

4.1.1 MAINTENANCE OUTAGES

An outage occurred in 2017 after oil was observed leaking from bearing cooling ports by SWBNO. During the outage, inspection of the turbine by General Electric lead to a number of maintenance activities and repairs. The turbine returned to operation in spring of 2018^[9].

On February 7, 2019 SWBNO electricians found that the TG 5 brushes were not riding on the collector rings properly and it appeared that the generator had thrusted away from the turbine. GE was on site beginning February 12, 2019 for an outage covering three major phases of work^[10]:

- Phase 1: Reduction Gear Inspection
 - Feb 10 Feb. 22, 2019
- Phase 2: Accessory Gearbox Repair and Startup Troubleshooting
 - o Feb. 25 Mar. 16, 2019
- Phase 3: Startup and Controls Troubleshooting
 - o March 18 April 14, 2019

During Phase 1 of the outage^[10], after the reduction gear work, the TG 5 liquid fuel system was traced down and the purge check valves were replaced. A liquid fuel run was attempted and failed. The decision was then made to focus on fuel gas operation.

Phase 2 of the outage began after damage occurred to the starting motor clutch hubs^[10]. After the repairs, several startup attempts were made, and repairs were made to several electrical controls and mechanical systems. After many failed startup attempts, the turbine was successfully started by bypassing the gas pressure ratio pilot valve with instrument air noting that the gas pressure ratio pilot valve required further inspection and testing. Phase 2 of the outage concluded, and Phase 3 work began. Phase 3 work included repairing the gas pressure ratio pilot valve, which was inspected and repaired by John H. Carter Company^[10]. The gas pressure ratio pilot valve required repair of a broken spacer and replacement of the diaphragm^{[10],[11]}.

After repair of the gas pressure ratio pilot valve, startup troubleshooting continued. Troubleshooting then occurred with getting the turbine to come up to speed when taking load, Adjustments were made

⁹ General Electric, "New Orleans SW&B Forced Outage 2017", Repair to return to service, June 18, 2019.

¹⁰ General Electric, "2019 Callout Outage – Reduction Gearbox – Starting Clutch – Controls Troubleshooting", June 15, 2019.

¹¹ Sewerage & Water Board of New Orleans, "Turbine 5 2019 Outage Report", October 1, 2019.



to the gas control valve linkages to original specifications and then the adjustments were reversed. At the end of the outage the turbine was proven to start, and hold loads of 0 - 12 MW.

A brief timeline summary of the maintenance activities on TG 5 is provided in Table 8 and a detailed timeline is provided in Appendix A.

Date	System	Maintenance Activity
March 2017	TG 5 System	Taken out of service for rehabilitation
Feb/March 2018	TG 5 System	Recommissioned following GE work
Feb 10 – Feb 22	TG 5 System	GE FieldCore Mobilized – Reduction Gear
2019	GE Phase 1 work	Inspection
Feb 10 – Feb 22	TG 5 System	Following the reduction gear inspection
2019	GE Phase 1 work	 Liquid fuel system was traced down
		Liquid fuel check valve replaced
		Purge check valve replaced
		TG 5 failed to run on liquid fuel after several
		attempts
		Liquid fuel troubleshooting postponed
Feb 17, 2019	TG 5 System	TG 5 was successfully run on gas fuel at the
	GE Phase 1 work	end of Phase 1
Feb 22, 2019	TG 5 System	Test run on gas
		 Issue with gas pressure
		Test run on diesel
		 Not successful
		Tried to start on gas after diesel run
		 Not successful
		GE begins demobilizing
Feb 25 – Mar 16	TG 5 System	Accessory Gearbox Repair and Startup
2019	GE Phase 2 work	Troubleshooting
		GE controls technician arrive to troubleshoot
		controls
March 15, 2019	TG 5 System	Gas pressure ratio pilot valve regulator
		 Actuated control valve manually to
		confirm operation
		 Regulator that controls the valve not
		operating properly
		Test ran machine and manually
		actuated the gas control valve by
		bypassing the regulator
Mar 18 – April 14	TG 5 System	Startup and controls troubleshooting
2019	GE Phase 3 work	 Repaired the pressure ratio pilot
		valve (PRV)
		Realigned the start motor

Table 8. Summary of Turbine Generator 5 Maintenance



Date	System	Maintenance Activity
		Troubleshot startup and fuel controls
Mar 18 – April 14	TG 5 System	The pilot valve (PRV) was inspected and
2019	GE Phase 3 work	repaired by John H. Carter (Carter)
		 Removed and sent to Carter on
		March 18
		• Found to have a broken spacer
		(regulator housing) and diaphragms
		Cast aluminum diaphragm spacer
		worn and cracked
		• Received from Carter March 23
Mar 18 – April 14	TG 5 System	At the end of the outage, the turbine was
2019	GE Phase 3 work	proven to start successfully and hold a load
		range of 0 – 12 MW



4.1.2 PRE-INCIDENT TG 5 OPERATION AND FINAL PREVENTATIVE MAINTENANCE

TG 5 ran continuously from October 3, 2019 to December 11, 2019 as reported by SWBNO Monitoring and Power Dispatching. On December 11th, TG 5 was shut down for preventative maintenance to:

- Brushes
- Oil changes
- Added hydraulic pressure indicator (analog)

The preventative maintenance that occurred on December 12 and the shop ticket, with the assignment name redacted, is shown in Figure 30.

TG 5 was test run on December 12th between 16:36 and 17:17. Operator 4 was responsible for the test run after the completion of preventative maintenance on December 12th. Operator 4 was training additional operators at the time, explaining the start-up steps to the operators as they were performed. After the ¼-turn shutoff valve was opened on December 12th the operator being trained then reset the annunciator and turbine trips in the control cabinet. Operator 4 described the start-up as not fast or slow, that it started up "just right, like the old days. It came up perfect." Operator 4 also stated (paraphrased), "Since the maintenance and overhaul, the machine has come up faster, not in a bad way, strong and fast like a new turbine. This time it did not come up fast, it came up like it did before. Not weak but like it did before the overhaul." The operator log from the December 12th test run is provided in Figure 31, with the names redacted.

Facility Maintenance: Electric Shop MUST FILL IN BOXES MARKED WITH "X" 1 (Excluding The Instrument Shop) Location Code (see be insertem): Bird description & instruction related to this work receipted by the assigning some constraints of the assigning some constraints of the so	 pervisoriteem & & & & &			
Description of work performed:		PUM	IPING & POWER OPERATIONS	
Decemption: Dechecker and cheen billed Ryging chearer and Replace burdier as needed			Plant Work Order Tracking Report	Page 2
Intel Strate was in the term Name Hours Name Hours Overling-Hours Overling-Hours Q Q Q Q Q Q Q Q Q Q	TICKET NO:85-201	Work Order No Initiated Date Date Completed Responsible Dept Initiated From Initiated From Activity Asset No Asset Type Work Details	2016400917 Status CL. Service Request No 12/12/2019 Initiated Time Activity Type CM 21/2/2019 Time CM PMPMTIN CLINCAL CLEAN AND/OR CALIBRAT EQP. Master Asset No	
	-A023580 use back for listing fk and additional comme		CLEAN COLLECTOR RING AND CHANGE BRUSHES AS NEEDED ON #6 TURBINE	R
For Electric Shop Use OMLY1 (Excluding The Instrument Shop)	MUNUNUN Antes	Action Taken	CLEANED, CHECKED BRUSHES, AND RINGS ON 16 TURBINE.	

Figure 30. SWBNO December 12 Turbine Generator 5 Maintenance Ticket and Tracking Report

SEWERAGE AND WATER BOARD OF NEW ORLEANS CAUSAL ANALYSIS AND RECOMMENDATIONS



Final Report

START	Orleans Sewerage and Water Bo Jumping and Turbine Operations	ard
START NAME:	<u> </u>	#5 GTG Start/Stop Log
STOP Print NAME:	Sign	T
STOP Print DATE: $12 - 12 - 19$	Sign	All data for this log
START TIME:	493 pm 4:36 pm	accurate and clearly written.
FLAME ON:	4-46 pm	Note:
UP TO SPEED:	4:53 pm	This log sheet is to
STOPPED AT:	5:10 pm	turbine until the unit
FLAME OUT:	5:17 pm	to be completed by
FUEL OIL TEMP: (DIESEL ONLY)		Engineer II.
FUEL OIL USAGE (TOP): (DIESEL ONLY)		Purpose for this run:
FUEL OIL USAGE (BOT): (DIESEL ONLY)		Rainload
ON TURNING GEAR: (COOLDOWN)		Emergency-
GAS METER START:	00008441	
GAS METER STOP:	0000 84 41	
		CHART BY D. B. ADAM Rev. MOR

Figure 31. Turbine Generator 5 December 12, 2019 Test Run Log Sheet



5 ANALYSIS

ABS Group conducted a site visit on May 26-27, 2020 to document the as-found condition of the turbine, which had remained mostly undisturbed since the December 14, 2019 incident. ABS Group then returned from July 14-16, 2020 to observe and document TG 5 systems testing including the startup simulation tests. The following systems tests were performed:

- Stop valve leakage test
- Gas pressure ratio valve time to close after opening ¼ turn shutoff valve
- Spark plug performance test by direct signal
- Start-up simulation tests, matrix provided below in Table 9

The results of the as-found documentation, systems testing, and startup simulation tests were utilized to analyze the TG 5 systems including the pneumatic controls, spark plugs, turbine compressor air, and fuel gas system as they related to the CAET scenarios. The results of the analysis of each system is discussed in further detail in the following sections.

Scenario	Control Air	CDP	¼-Turn Shutoff	Gas pressure ratio valve @ Start	Note
1	As Found 30-35	0	Open	Closed	
2	As Found 30-35	~5	@ 1m into Purge Timer	In Motion / Open	
3	As Found 30-35	~5	1.5M Before Auto	In Motion / Open	See Startup Figure, 1.5 M is duration of time to crank to 750 rpm and start sequence. Simulate 'Auto' and Open 1/4 turn at same time.
4	As Found 30-35	~5	Beginning of Firing Timer 2F	In Motion / Open	

Table 9. Start-up Simulation Tests

5.1 PNEUMATIC CONTROLS

During as-found documentation of the turbine and equipment, control air to the turbine was restored and the pneumatic controls identified in Table 5 of Section 2.1.2 were inspected. All VPRs were observed to be within reasonable limits of the specified settings from the schematic piping diagrams with the exception of VPR-10 as shown in the two right hand columns in Table 10. VPR-10 is the control air supply for the gas pressure ratio pilot valve. The specified value is 20 psig ⁺/- 0.5 psi as shown from the schematic piping diagram in Figure 32 and the pressure was observed to be 30 psi at the VPR-10 regulator and 35 psi as measured by the pilot supply pressure gage as shown from photographs taken during the as found inspection in Figure 33.

SEWERAGE AND WATER BOARD OF NEW ORLEANS CAUSAL ANALYSIS AND RECOMMENDATIONS



Final Report Table 10. Turbine Generator 5 Dry Air VPRs

					As Found	
Name	From	То	P&ID - Sheet	Specified Setting	Pressure	
VPR-2	Referenced on P	&ID (916B455-Sheet 7)	916B455-Sheet 7	85 psig	Unobserved	
VPR-3	Air Supply	TEMR transmitter	916B455-Sheet 5	20 psig	21 psig	
VPR-4	Air Supply	Butterfly control valve	916B455-Sheet 5	20 psig	22 psig	
VPR-5	Air Supply	Air Supply Pneumatic 916B455-Sheet 5 Controller 916B455-Sheet 5		20 psig	21.5 psig	
VPR-6	Air Supply	Pneumatic Controller	916B455-Sheet 5	See Cont. Specs.	No gage	
VPR-7	Within the pneumatic temperature relay		916B455-Sheet 4	32 psig,⁺/₋ 0.5 psi	36 psig	
VPR-8	Air Supply	OT trip	916B455-Sheet 4	62 psig,⁺/₋ 0.5 psi	66 psig	
VPR-9	Air Supply	Fuel Gas Control Valve	916B455-Sheet 6	35 psig,⁺/₋ 0.5 psi	34 psig	
VPR-10	Air Supply	Gas pressure ratio pilot valve	916B455-Sheet 6	20 psig,*/_ 0.5 psi	30 psig at regulator 35 psig at pilot	



Figure 32. VPR-10 Specified Valve Settings

SEWERAGE AND WATER BOARD OF NEW ORLEANS CAUSAL ANALYSIS AND RECOMMENDATIONS



Final Report





5.2 ELECTRICAL PANEL AND RELAYS

During the startup simulations the electrical panels, relays and timers functioned as anticipated. Relay 14 HM would stick and not open at the conclusion of some runs requiring an operator to tap on the relay to return the relay to the open position. However, this issue would not affect the startup sequence prior to firing the TG.

5.3 SPARK PLUGS

During startup simulation testing the spark plugs were removed from TG 5 so that they could be observed during each simulation of the start-up sequence. Both spark plugs arced as anticipated during the simulations, as shown in Figure 34, and the air pressure that inserts the plugs into the combustion chamber during normal operation was also observed to be operating normally. The spark plugs operated as anticipated, therefore, normal gas flow with malfunction ignitor was contradicted and determined to have very low plausibility.



Figure 34. Turbine Generator 5 Ignitors During Test Simulation



5.4 TURBINE COMPRESSOR AIR INTAKE

During the first post incident inspection of TG 5 in late December 2019 by ABS Group, an accumulation of insects on the turbine compressor air intake screen was observed. During as-found inspection the compressor air intake duct was opened behind the air intake screen for further inspection. Both the outside and inside of the compressor air intake are shown in Figure 35. During discussions between ABS Group, SWBNO, and General Electric, General Electric confirmed that a significant obstruction of compressor air intake flow would create a pressure drop and likely result in damage to the air intake ducting (e.g., collapsing the ductwork) as a result. Because no foreign objects or insects were observed behind the air intake screen, the insects appeared to have been in place for a substantial amount of time (longer than the period of time between the December 12th and 14th startups), and the lack of observable damage to the compressor air intake ducting, reduced compressor intake air flow was contradicted and determined to have very low plausibility.



Figure 35. Compressor Air Intake Screen and Ducting

5.5 FUEL GAS SYSTEM

Possible causes of excess fuel gas flow during the start-up attempt of December 14th were investigated and included: (1) gas flow during the purge step, and (2) abnormally high fuel gas flow during the firing attempt as shown in the applicable portion of the CAET in Figure 36 (the complete CAET is provided in Appendix B). Both branches require one of the fuel gas system valves to malfunction. Branch 2.1.1, gas flow during the purge, was contradicted because this event required both the gas pressure ratio valve to be open during the purge, which is believed to have occurred, but the fuel gas stop valve and fuel gas control valve must also be open during the purge, neither of which were observed during testing. Further contradicting gas flow during the purge is that Operator 1 stated that the explosion occurred at



the end of the first firing sequence and introduction of fuel gas during the purge or an inadequate purge would likely result in the explosion occurring at the beginning of the firing sequence. Therefore, due to the normal fuel gas stop valve and fuel gas control valve operation and the timing of the event, gas flow during the purge step was contradicted and determine to be very low plausibility.

Abnormally high fuel gas flow during the first firing attempt was determined to be highly plausible due to the gas pressure ratio valve remaining open as a result of slow control by the pressure ratio valve pilot that may be further exacerbated by any delay in opening of the ¼-turn shutoff valve.

SEWERAGE AND WATER BOARD OF NEW ORLEANS CAUSAL ANALYSIS AND RECOMMENDATIONS





Figure 36. CAET Excess Fuel Gas Flow Major Branches



5.5.1 GAS PRESSURE RATIO VALVE AND PILOT

The gas pressure ratio valve and pilot, shown in Figure 37, regulates the downstream fuel gas pressure before the stop valve, based on compressor discharge pressure (CDP). The pilot valve inputs include: (1) control air supply, specified to be 20 psi +/- 0.5 psi as discussed in Section 5.1, (2) turbine CDP, and (3) downstream fuel gas pressure before the stop valve (P2). The control output is control air to the gas pressure ratio pilot valve to adjust the gas pressure ratio valve position to achieve the regulated downstream fuel gas pressure, P2.



Figure 37. Turbine Generator 5 Gas Pressure Ratio Valve and Pilot

The gas pressure ratio pilot valve controller controls the downstream fuel gas pressure utilizing the following specified linear relationship:

$$P2 = 1.4 \cdot CDP + 5.88$$
 [Eq. 1]

Where downstream gas pressure is supposed to be regulated to be 5.88 psig when CDP is 0 psig. This offset pressure is referred to as the zero CDP offset. For a non-zero CDP, the downstream fuel gas pressure is specified as 1.4 times the CDP, plus the zero CDP offset. GE Control Specifications 114A9016 define the zero CDP offset and pressure ratio and is provided in Figure 38^[12]. The GE outage report Section 3.8^[10], provides a condition description of the gas pressure ratio valve pilot and confirms the control specification of 5.88 psi zero CDP offset and notes than several different offsets were tested but ultimately the pilot was set to hold an offset of approximately 6 psi. Appendix 5 of the GE outage report contains a troubleshooting summary and startup and operational readings, shown below in for TG 5, dated April 16, 2019 at the end of Phase 3 of the GE outage work as shown in Figure 40^[10].

¹² General Electric, Control Specifications, 114A9016, Dec. 1, 2019.

SEWERAGE AND WATER BOARD OF NEW ORLEANS

CAUSAL ANALYSIS AND RECOMMENDATIONS



Final Report

	GENERAL@ELECTR	C 1/44 90/6
	TO THA	UFICATIONS
	114A9016 CUNTROL SPEC	ISINGLE SHAFT MICH.)
	Distant Agencies and Ston coundary, Sp. 120 300-	74000 14 127724 Walnut
	The To LOO IN BUT-H TEN LINES 3 600 R PM	NO. 46) - 40960
	WITHIN DAME FUEL GAS - 2605TORDATION - 1958 0.591. 37 1705 WIESS DOTALAR - 19452 870 (0011- 1998835 1997	0mo 64 48 334 61
GAS FUEL SISIEM	SPEED CONTROL SYSTEM	P/66455
GAS CONT. VALVE: BATING 4'0 - 300#	111 - 2740 Pielo _3870 004 TH	C1+3+5-546 = 0. 195
VALVE 4.5 DIA TYPE SKIRTED VENTURA	10100 NEWL # 100 - 413/50 A. F 6.2	9. May South
	11 100	STAT OF BRIDE PLOT
SIZEPRESSPSIG	TOTA W LADIAL De 38 / BORNES THE PERDS. 20hs	WALTER US
TOTAL FUEL NOZ. AREA 3.3717 IN CAL	1 2 A Surn 6 3424 (18.57-24) TO CONNER A	CONDITING FUEL
MIN FUEL TYPE RELAY SALAS	THE STACKED	I ZING MOTHE IS USED
STOP I / LALA LAL / VALVE /	134 X 134 6 1715	1.4.2 -328 SW. 0 3-6
V.C.O. 2 2 2PSIG. N.C.O. 2 2 4 TRAVEL	TATIST DE HARD PASS PES	L HIMORE SEE INC. 4.534
TYPE SIE Y.C.ANALVE	The manage	in ide . aft igt
FUEL 160 +20 PSIG 150 0E TEMP	The for the first for the All there for	fore ofer f. Strand
SUPPLY TE ED _ TOTO, DE C MAX.	GAS FUEL SYSTEM OIL	FUEL SYSTEM
PRESSURE / RATIO VALVE	THE AS ON THE SECONDER STUD	solution dennes - of face
BATING 4 SOUTTYPE LESLIE ENVE S	This 10.50 Mars 140 min 1814 million	65-0 110 W 10 19/ 19/
PRESSURE 1.40_ PRESET 2.88_ PSIG.	METER THE MED'S - WHEN LAND WHEN THE	5 - 17 A no 19 - 25 - on 20 - 10 - 1
BY PASS SYSTEM : CUT/OUT/ / IMENUAL	The fit for the fit was	AND SHE MAY
aby / losid . RELID / Josia	14114 - 140 - 114 LEQ - E 147 - 114 LEQ - 2.03	All and an a Margan
MAIN - FOIL / VALUE	Ante 140 sater J.B. san Der Manna Set	A OA STORY
WALVE SIZE + TYPE		Jar had The
GAS STOP VALVE BODY 4"-300 #	111 111	H XEDVING THE 200
VALVEA.5 DIA HENTILOLUSE 162	141 4 SANANDALIT 1.62	the fails May sound
SIZE I STREET LIFT	Ellen and and and	
SIZE PRESS PRESS PRESS PRESS PRESS.	- 100 LING 2(+) SCHEMEOTADY	mm mmmt mml
W12 12-7-14	To To	0

Figure 38. Gas Pressure Ratio Pilot Valve Specified Zero CDP Offset and Pressure Ratio



GE Power Power Services

3.8 PRESSURE RATIO PILOT VALVE (CONTROL VALVE)

Part Condition: Poor

Part Condition Description

The pressure ratio pilot valve controls the pressure ratio valve. The pilot valve has two input signals: Compressor Discharge Pressure and Fuel Gas Pressure before Stop Valve. It compares these two signals with a fixed ratio diaphrogm of 1.4:1. Additionally, the pilot valve has a spring built into the valve stem that can be used to adjust the offset of the pressure ratio. Because the pressure ratio is fixed, this spring is the only adjustment on the pilot valve and is meant to make minor adjustments to meet the control specifications.

During startup troubleshooting, the functionality of the pilot valve was questioned, and it was inspected by a technician from John H. Carter. The pilot valve was found to have holes in its diaphragms and a cracked diaphragm spacer. Replacement diaphragms were ordered from Leslie Controls, and John H. Carter completed the valve repair by machining a new spacer. The valve was tested in the John H. Carter shop and is functioning correctly. Additionally, the CDP line that connects to the pilot valve was cleaned out with compressed air and was found to have a fair amount of dirt and debris.

As stated previously, the pilot control valve has only one adjustment. The spring on the valve stem can be adjusted to create an offset pressure. In other words, the pressure that the pressure ratio valve will hold when there is zero CDP (during startup). The control specification calls for an offset of 5.88 psi. During startup troubleshooting, several different offsets were tested, but ultimately the pilot valve was set to hold an offset of approximately 6 psi.

Figure 39. GE Outage Report Pressure Ratio Pilot Valve Condition Description



Turbine Operating Data & Troubleshooting

Date 4/16/2019

Turbine Serial No.

o. 127724

Prepared by

C. Beason

Startup & Operation Readings

Fuel Condition	Speed (rpm)	S1 Stroke (inch)	GCV Stroke (inch)	FGP before SV (psi)	FGP after GCV (psi)	CDP (psi)	Lube Oil Press. (psi)	Exhaust Temp Avg	Exhaust Temp. Pr.	CD Totalizer Output	Temp. Relay Output	LP Selector Output
Turning Gear	0	0.0"	0.0"	0	0	0	25	545	30	0	30	35
Acceleration	1900	0.300"	0.75"	0 - 105	0 - 62	0 - 60	150	545	30	0	30	32
FSNL	3620	0.020"	0.35"	105	62	60	160	545	30	0	28	31
5MW Load	3600	0.080"	0.55"	110	70	64	150	545	30	0	28	32
12.3 MW	3870	0.170"	0.677"	125	75-80	75	155	545	40*	0	30	

Figure 40. GE Turbine Startup Record



Startup Troubleshooting Summary

Issue	Cause / Solution
Turbine repeatedly tripping during purge timer	Starting motor misalignment and/or 33CS limit switch giving faulty reading
Synchronizing Motor not raising after warmup timer	84FL limit switch was out of position, not resting on fuel transfer lever
Pressure Ratio Valve not reacting to changes in fuel gas supply pressure during offline vent test	Pressure Ratio Pilot Valve has torn diaphragms and a cracked spacer was not properly regulating the CDP to FG pressure ratio. Dirt also found in AD-4 line.
Solenoid Valves not actuating when they should be in sequence	Loose wires were found in junction boxes and poor connections on top of solenoids.
Fuel selector lights for liquid fuel and gas fuel were both illuminated	Fuel selector relay 84TGX had a burnt coil that needed to be replaced
Various timers not operating during the sequence	Several timers had loose wires or broken connectors. Some needed to be replaced all together.
Failure to fire	After the 2TV timer started and ran for 2 minutes the contacts did not change state and send the correct signal to the 2TVY relay and the 2F relay
Light smoke coming from turbine after startup	Auxiliary lube oil pump had been running without vapor extractor for about 2 hours the previous day. Without vapor extractor on to create vacuum pressure, the bearing oil seals will not work.
Turbine could not be raised to 3850 rpm after startup complete	Had to move sync motor stop collar so that max speed with no load is 3850 rpm
Turbine tipping at 1200 rpm without alarms	Motor Control Center door switches can trip turbine during startup. One was repaired and the other was jumpered.

Figure 41. GE Turbine Operation Readings



During the startup simulation testing, the downstream fuel gas pressure was recorded for 0 psig and ~ 8 psig CDP and plotted with the GE Operation readings from Figure 40. The as-found measurements are consistent with the GE operational data from April 16, 2019 that indicate a zero CDP offset of ~ 29 psi or roughly 5 times the specified value of 5.88 psi and not the 6 psi offset mentioned in the outage report. The pressure ratio was ~1.3, which is within 10% of the specified pressure ratio. For reference, the grey line in Figure 40 represents the zero CDP offset and pressure ratio from the control specification. Therefore, the gas pressure ratio pilot valve was providing approximately 5 times the fuel gas pressure before the stop valve (P2) during firing when the CDP is near zero, which is the case as the TG initially fires. The excess fuel gas pressure (P2) was observed in the as-found configuration and although the contribution to the incident was moderate the excess pressure was determined to be a causal factor.

SEWERAGE AND WATER BOARD OF NEW ORLEANS CAUSAL ANALYSIS AND RECOMMENDATIONS



ABS Group

30 November 2020

Figure 42. Gas Pressure Ratio Pilot Valve CDP vs Downstream fuel Gas Pressure P2



The gas pressure ratio pilot valve measures CDP and controls the downstream fuel gas pressure before the stop valve with a specified offset of ~ 6 psig and a measured offset of ~29 psig. Regardless of the zero CDP offset, when the ¼-turn shutoff valve is opened immediately prior to starting the turbine just after the operator notifies Central Control, the expected position of the gas pressure ratio valve is 100% open. The gas pressure ratio valve control system is trying to achieve the target pressure of the zero CDP offset, while the actual pressure is 0 psig. When the ¼-turn shutoff valve is opened, the fuel gas pressure before the stop valve will increase immediately to the supply fuel gas pressure, 200 to 220 psig, when the gas pressure ratio pilot should control the gas pressure ratio valve to close due to the excess fuel gas pressure, P2. During testing of TG 5, fuel gas pressure was simulated using an air compressor and the ¼-turn shutoff valve was opened without starting the turbine as indicated in Table 11. The time for the pilot to control the gas pressure ratio valve to fully closed was measured.

After establishing fuel gas pressure by opening the ¼ turn shutoff valve, the gas pressure ratio valve position remained 100% open for ~1.6 minutes and then required an additional ~3.2 minutes to fully close as shown in Figure 43. The total time after opening the ¼ turn shutoff valve until the gas pressure ratio valve achieved the fully closed position was ~4.8 minutes.

System	Condition 1	Condition 2
1/4 Turn Shutoff	Closed	Open
Stop Valve	Closed	Closed
Gas Pressure Ratio Valve	Open	Measure time to close
CDP	0 psig	0 psig
VPR-10 Supply Control Air (As Found)	30 to 35 psig	30 to 35 psig

Table 11. Ga	s Pressure Ratio	Valve Close	Test after	Establishing	Fuel Gas	Pressure
TUDIC II. Gu	STICSSUIC Matio		i cot unter	Locustioning	I aci Gasi	1C35GIC

SEWERAGE AND WATER BOARD OF NEW ORLEANS CAUSAL ANALYSIS AND RECOMMENDATIONS



Final Report



Figure 43. Gas Pressure Ratio Valve Position vs Time after Establishing Fuel Gas Pressure



Three start-up scenarios were simulated during testing as detailed in Table 12. First, the ¼-turn shutoff valve was opened, and the pilot allowed to control the gas pressure ratio valve to the fully closed position prior to initiating the start-up simulation. This is not the standard operating method; however, it does allow the gas pressure ratio valve to achieve the expected pre-start-up position, which is fully closed. Second, the ¼-turn shutoff valve was opened 1.5 minutes prior to the beginning of the purge sequence. This is approximately the time it takes the TG to accelerate to ~ 750 rpm by the cranking motor. This was performed to simulate the SWBNO operating procedure of opening the ¼-turn shutoff valve immediately prior to starting the turbine. Finally, the ¼ -turn shutoff valve was opened late, 1 minute into the purge sequence. Pilot output control pressure signal and the position of the gas pressure ratio valve were plotted versus the sequence time as shown on the start-up diagram in Figure 44.

Scenario	Description	Control Air	CDP	¼-Turn Shutoff Opened	Gas Pressure Ratio Valve Condition @ 1 st Firing	Note
1	¼ turn shutoff valve opened well before auto sequence started (not normal practice)	As Found 30-35	0	Prior to Sequence Start	Closed	Gas pressure ratio valve is closed prior to starting sequence (not the normal practice)
2	¼ turn shutoff valve opened at start of auto sequence (normal practice)	As Found 30-35	~5	1.5 min. Before Purge	In Motion / Open	See Startup Figure, 1.5 min. is duration of time to crank to 750 rpm and start sequence. Simulate 'Auto' and Open 1/4 turn at same time.
3	¼ turn shutoff valve opened after auto sequence started (not normal practice)	As Found 30-35	~5	@ 1min. into Purge Timer	In Motion / Open	

Table 12. Test Case Scenarios

SEWERAGE AND WATER BOARD OF NEW ORLEANS CAUSAL ANALYSIS AND RECOMMENDATIONS



ABS Group

30 November 2020



Figure 44. Automatic Start Up and Test Scenario – Establishment of Fuel Gas Pressure



Results for test scenario 1, plotted in Figure 45, indicate that when the pilot is allowed to control the gas pressure ratio valve to a fully closed position prior to start-up of the turbine and prior to the firing sequence that both perform as expected with the pilot controlling the gas pressure ratio to approximately 25% open during the firing sequence.



Figure 45. Test Scenario 1 - Gas Pressure Ratio Valve Position and Pilot Output Pressure

Results for test scenario 2, which represents the normal sequence for turbine startup, are presented in Figure 46. This reveals many facets of the as-found operation of the gas pressure ratio pilot. The pilot output control pressure, represented by the blue line in Figure 46, begins at the as-found control air supply pressure of \sim 30 psig and the gas pressure ratio valve remains 100% open until the control air output pressure drops to 18 psig. GEI-40960 page 676^[10], reproduced in Figure 47, shows a cross-section of the gas pressure ratio pilot and is stamped with "0-18 operational range 1.4 to 1 ratio". The 1.4 to 1 ratio is understood to be the linear slope of downstream fuel gas pressure to CDP and the 0 to 18 range is suspected to be the range of control pressures to manipulate the gas pressure ratio valve position. In any case, inspection of the scenario 2 test results in Figure 46 clearly indicate the gas pressure ratio valve position does not begin to respond to the pilot control pressures until it falls to 18 psig, consistent with the 0-18 range in Figure 47. The result is that the high input control air pressure identified in Section 5.1, results in the delayed onset of gas pressure ratio valve movement, which is the second causal factor. The third causal factor identified during test scenario 2 is that the pilot is slow to control the gas pressure ratio valve, as indicated by the time required for the pilot to control the gas pressure ratio valve position. This results in the gas pressure ratio valve being opened in excess of that required for firing of the turbine.

SEWERAGE AND WATER BOARD OF NEW ORLEANS CAUSAL ANALYSIS AND RECOMMENDATIONS



Final Report



Figure 46. Test Scenario 2 - Gas Pressure Ratio Valve Position and Pilot Output Pressure





Figure 47. Gas Pressure Ratio Valve Pilot Drawing from GEI-40960

Test scenario 3, opening the ¼ turn valve late, results in an even larger opening position of the gas pressure ratio valve at the onset of firing as illustrated in Figure 48, which is the fourth causal factor.





Figure 48. Test Scenarios - Gas Pressure Ratio Valve Travel vs Percentage of Fuel Gas Flow



5.5.2 STOP VALVE

Observation of the fuel gas stop valve performance during start-up simulations indicated that the stop valve opened over a period of approximately 6 seconds during the onset of firing and closed rapidly, less than 1 second, at the end of the firing sequence. The stop valve remained closed during the purge cycles.

A leak test was also performed by opening the ¼-turn shutoff valve, pressurizing the volume upstream of the stop valve, then closing the ¼-turn shutoff valve and monitoring the pressure between the ¼-turn shutoff valve and the stop valve over a period of 10 minutes. Table 13 shows that the rate of pressure decay was approximately 1 psi per minute and a total of 10 psi over the duration of the 10 minute test as shown in Figure 50. The volume of piping between the two valves is relatively small and the rate of gas leakage low.

The fuel gas stop valve performance was nominal. Therefore, malfunction of the fuel gas stop valve was contradicted and determined to be very low plausibility.



Figure 49. Fuel Gas Stop Valve Operation During Start-up Simulation

Timo	Pressure Before	
Time	Stop Valve	
0 min	167 psi	
2 min	165 psi	
5 min	162 psi	
10 min	157 psi	

Table 13. Fuel Gas Stop Valve Leak Test Results

SEWERAGE AND WATER BOARD OF NEW ORLEANS CAUSAL ANALYSIS AND RECOMMENDATIONS



Final Report





5.5.3 GAS CONTROL VALVE

A dial indicator was placed on the gas control valve to monitor the movement of the valve during startup testing. This test was recorded using a camera at 60 fps. The gas control valve is a fast-acting valve with a specified opening position of 0.315 inches during firing of the turbine. The gas control valve was observed to operate nominally during all simulated firing attempts, as shown in Figure 51. Therefore, malfunction of the gas control valve was contradicted and determined to be very low plausibility.



Fuel Gas Control Valve Travel ~0.3" • Consistent with the specification ۲ LDE STTIDES - CAS & OIL KIN. HID. CONTROL PLOCP FUCP VIN. FUEL CTL. LDG FUEL CONDITION PRIMART SECONDART ELECTRICAL DEVICES EXERCITED TEOP. GAS CONTROL VALVE PRIMARY ELECTRICAL -----SEE NONE 0 0 C.O.T. C.O.T. C.O.T. C.O.T NONE . 110 POCD + 20HD+65MS TO 84FL 20CF+20FL 0.083 0,349 0.090 0.408 0.053 OIL 88 TIRING 20FG 013 ò 0.349 0.010 0:408 0.315 SOCD+SOHD 0.349 0.060 0 0.299# C.O.T.# 20CD+20HD+20WG # 20CF +20FL ALL CC WARN-UP CAS 0 0.349 0.010 0.299 0.230 20CD+20HD+20WG 20FG 20CD+20HD+65MS TO84FL 0.083 20,CF + 20FL OIL 0.349 0.090 0.408 0.053 DD CCELERATI GAS 0.307 0.349 0.010 0.408 0.900 20CD +20HD +65MS TO 84FG 20FG 0.349 0.060 20CD+20HD 20CF+20FL 0 0 0.408 0.05.3 оц B MIN. FUEL 045 0.349 0.010 0.408- 0.315 20CD+20HD 20FG 0 0. 0.036 0.008 0.349 0.073 0.408 0,053 20 CD +20HD 20CF +20FL or 11 HO LOLD 0.036 0.008 0.349 0.010 0.408 0.384 20,CD +20HD 013 2OFG OIL 0.436 0.092 0.349 0.218 0.406 0.053 20CD +20HD 20CF + 20FL ň 00 4/4 101D als 0.436 0:092 0.349 0.010 0.408. 1.147 20CD+20HD 20FG 0.491 0.103 0.349 0.238 0.408 0.053 20CD+20HD 20CF + 20FL OIL KAX. QUOTED FUEL FLOW HH 0.491 0.103 0.349 0.010 0408. 1.252. 20CD+20HD 20FG 0.590 0.124 0.349 0.274 0.408 0.053 20CD+20HD 20CF+20FL OIL HAL. FEQ'D. STROKES 33 0.349 0.010 0.408 1.440 SOCD+SOHD aus 0.590 0.124 20FG GENERAL (ELECTRIC 675D399 9 1 AB UNLESS LEVER SETTING DIAGRAM 675D399 1 IRST MADE FOR NL 71427589 Closed NEW ORLEANS SEPARADE & WATER BOARD Open TB. No. 1277

Figure 51. Gas Control Valve Position During Startup Simulation


6 CAUSAL FACTORS AND RECOMMENDATIONS

The CAET was used to identify the most plausible causal factors that led to the TG 5 explosion on December 14. The causal factors and the recommendations are shown in Table 14 below.

Causal Factor	Recommendations
Causal Factor 1 - VPR-10 supply control air to the gas pressure ratio pilot valve set 10 psi above the specified value of 20 psi +/- 0.5 psi	 Recommendation 1: Set and maintain gas pressure ratio pilot valve control air to correct value Recommendation 2: Develop and use management of change to control and maintain future changes of the control system
Causal Factor 2: Gas pressure ratio pilot valve fuel gas pressure offset (~20 psi) above specified value of 6 psi.	 Recommendation 3: Set and maintain Leslie pilot to proper zero CDP fuel gas pressure offset for operation of the Turbine Recommendation 2: Develop and use management of change to control and maintain future changes of the control system
Causal Factor 3: The gas pressure ratio pilot valve pilot is slow to adjust to inputs and control the gas pressure ratio valve.	 Recommendation 4: Requalify both the Leslie and Pilot to specified operation by a certified vendor. Recommendation 5: Replace both the Leslie and Pilot with a modern gas ratio valve and controller.
Causal Factor 4: Fuel gas supply ¼ turn shutoff valve may not have been opened until after operation selector switch set to auto	 Recommendation 6: Add the following permissives to begin the startup sequence (Set Selector to Auto). Fuel supply ¼ turn shutoff valve open. No combustible gas in exhaust duct near combustion chamber prior to onset of firing. Recommendation 7: Perform HAZOP of new / modified controls system to identify and mitigate potential excessive fuel flows during startup sequence.

Table 14. Causal Factors and Recommendations



Causal Factor	Recommendations
Causal Factor 5: Gas pressure ratio valve is slow to adjust to pilot control signal.	 Recommendation 4: Requalify both the gas pressure ratio valve and pilot to specified operation by a certified vendor OR replace both the gas pressure ratio valve and pilot with a modern gas ratio valve and controller. Recommendation 8: Add the following permissive to begin the startup sequence (Set Selector to Auto). Gas pressure ratio valve closed.



7 REFERENCES

1 Sewerage & Water Board System Overview Presentation, January 2018.

2 Sewerage & Water Board Power Generation and Drainage System FAQs, 14 August 2017.

3 Vanden Heuvel, Lee et al., "Root Cause Analysis Handbook", ABS Consulting, Rothstein Associates Inc Publishers, 2008.

4 GEI-40960, "Gas Turbine-Generator Unit 20,200 KW Gas Turbine No. 127724, Generator NO. 8300411", Sewerage and Water Board of New Orleans Purchaser's Order NO 198-W, Gas Turbine Department General Electric, Schenectady, N.Y., 1960.

5 GEI-77036A, "Gas Turbine Generator 20,200 KW", Medium Voltage Switchgear Department, General Electric, Philadelphia, PA, August 1960.

6 Sewerage and Water Board of N.O. DWG No. 10948-W-2, "Sewerage & Water Board Gas Turbine Start-Up Sequence", July 8, 1963.

7 GE Schematic Piping Diagrams, 916B455, July 15, 1959.

8 Sewerage and Water Board of New Orleans, Carrollton Water Plant security camera footage from 18 different cameras, December 14, 2019.

9 General Electric, "New Orleans SW&B Forced Outage 2017", Repair to return to service, June 18, 2019.

10 General Electric, "2019 Callout Outage – Reduction Gearbox – Starting Clutch – Controls Troubleshooting", June 15, 2019.

11 Sewerage & Water Board of New Orleans, "Turbine 5 2019 Outage Report", October 1, 2019.

12 General Electric, Control Specifications, 114A9016, Dec. 1, 2019.



APPENDIX A – TIMELINES





No.	Date	Time	ltem	Event	Ref.
10	1959		TG 5 System	Design approved for	
				construction	
20	August 1960		Startup	Procedure developed by GE	5
			Procedure		
30	July 8, 1963		Procedure	Startup procedure diagram	6
				generated by R.M. McKay,	
				Drawing No. 10948-W-2, SKE-	
				357	
40	March 2017		TG 5 System	Taken out of service for	
				rehabilitation	
50	Feb/March 2018		TG 5 System	Recommissioned following GE	
				work	
60	February 6, 2019		TG 5 System	Electricians perform PM on	11
				the generator.	
70	February 7, 2019		TG 5 System	SWBNO personnel met GE	
				crew and gave tour	
80	Feb 10 – Feb 22		TG 5 System	Reduction Gear Inspection	10
	2019		GE Phase 1		
			work		
100	Feb 10 – Feb 22		TG 5 System	GE FieldCore Mobilized	10, 11
	2019		GE Phase 1	 Inspected reduction gear 	
			work	box	
				 Lose babbitt on 	
				the gears	
				 Upper halves of 4 	
				reduction gear	
				hearings inspected	
				o I hrust bearing	
				pads inspected	
				 Bearings, journals, oil 	
				deflectors cleaned and	
				measured	
				Reduction gearbox casing	
				and holt holes cleaned	
			7050	Gearbox reassembled	10
110	Feb 10 – Feb 22		IG 5 System	Following the reduction gear	10
	2019		GE Phase 1 work	inspection	
				Liquid fuel system was	
				traced down	
				 Liquid fuel check valve 	
				replaced	



No.	Date	Time	ltem	Event	Ref.
				 Purge check valve 	
				replaced	
				TG 5 failed to run on liquid fuel	
				after several attempts	
				Liquid fuel troubleshooting	
				postponed	
120	Feb 17, 2019		TG 5 System	TG 5 was successfully run on gas	10, 11
			GE Phase 1 work	fuel at the end of Phase 1	
130	Feb 18-21, 2019		TG 5 System	Oil leak on the gearbox observed.	11
				GE reopened the gearbox	
				Cleaned surfaces	
				 Applied new sealant and 	
				closed	
140	Feb 22, 2019		TG 5 System	Test run on gas	11
				 Issue with gas pressure 	
				Test run on diesel	
				 Not successful 	
				Tried to start on gas after diesel	
				run	
				 Not successful 	
				GE begins demobilizing	
150	February 23, 2019		TG 5 System	Turbine test failed again	11
			SWBNO	 Suspected a controls issue 	
				 GE looking at providing a 	
				controls expert	
160	February 24, 2019		TG 5	SWBNO Facility Maintenance and	11
	, .		SWBNO	Electric Shop cannot find issue	
				with turbine controls	
				Gear reduction gearbox leaking	
				again	
170	Feb 25 – Mar 16		TG 5 System	GE controls technician arrive to	11
	2019		GE Phase 2 work	troubleshoot controls	
				SWBNO electrician pointed issue	
				out an issue with door switch on	
				Switch adjusted to allow	
				for continuity and a second and w	
				for earlier engagement	
				Switch not part of the	
				problem	
180	Feb 25 – Mar 16		TG 5 System	The 33CS Starting Clutch Limit	10, 11
	2019		GE Phase 2	Switch was adjusted by	
			work	SWBNO ~Feb 25th.	

l



	Final Report				
No.	Date	Time	Item	Event	Ref.
				On subsequent startup the motor started before the	
				clutch was engaged	
				• Jaw teeth on the clutch	
				hubs were heavily	
				damaged	
				This initiated the Phase 2	
190	Feb 25 - Mar 16		TG 5 System	Outage work by GE	10
150	2019		GE Phase 2 work	Startup Troubleshooting	10
200	Feb 25 – Mar 16		TG 5 System	GE FieldCore removed the	10, 11
	2019		GE Phase 2 work	 accessory gearbox cover to access the damaged clutch Both clutch hubs were removed #1 gear and shaft removed Jaw teeth on the clutch hubs were repaired by SWBNO machine shop Feb 27 GE FieldCore then: Bainstalled the hubs and 	
				 Reinstalled the hubs and the #1 gear shaft Reassemble the Accessory gearbox 	
210	Feb 25 – Mar 16 2019		TG 5 System GE Phase 2 work	 Phase 2 startup attempts testing and several repairs to electrical, controls, mechanical issues First startup attempt March 4 Fuel transfer relay and two timers replaced with customer spares A lose ground wire shared by several solenoid valves fixed Starting motor clutch assembly tested, adjusted to meet specifications Clutch piston replaced March 8 	10, 11



Final Report No. Date Time ltem Event Ref. • **Instrument Air lines** disconnected and blown out Compressor discharge • pressure (CDP) signal air lines disconnected and blown out 220 March 15, 2019 TG 5 System Gas pressure control pilot valve Actuated control valve manually to confirm operation Pllot that controls the valve not operating properly Test ran machine and manually actuated the gas control valve by bypassing the regulator Feb 25 – Mar 16 10 230 TG 5 System After many failed startup attempts 2019 GE Phase 2 work the turbine was started by bypassing the pressure ratio valve with instrument air The pilot valve needed further inspection and Phase 2 outage concluded 240 Mar 18 – April 14 TG 5 System Startup and Controls 10 GE Phase 3 work 2019 Troubleshooting Repaired the pressure • ratio pilot valve (PRV) • Realigned the start motor Troubleshot startup and • fuel controls 250 Mar 18 – April 14 TG 5 System The pilot valve (PRV) was 10, 11 2019 GE Phase 3 work inspected and repaired by John H. Carter (Carter) • Removed and sent to Carter on March 18 Found to have a broken spacer (regulator housing)

and diaphragms



No.	Date	Time	Item	Event	Ref.
				Cast aluminum diaphragm	
				spacer worn and cracked	
				Received from Carter	
				March 23	
260	Mar 18 – April 14 2019		TG 5 System GE Phase 3 work	 The turbine repeatedly tripped during the purge timer Accessory gearbox cover removed to investigate the clutch assembly Starting motor found to be misaligned with the accessory gearbox Alignment move was made to bring alignment within specification Clutch assembly and limit switch were reset and tested independently Gearbox reassembled 	10
270	Mar 18 – April 14 2019		TG 5 System GE Phase 3 work	Several other electrical and controls problems were identified and fixed Liquid fuel limit switch Synchronizing motor resistor Startup timer	10
280	Mar 18 – April 14 2019		TG 5 System GE Phase 3 work	 The turbine could still not be manually raised to 3850 rpm at full speed no load (FSNL) because of the stop collar on the sync motor shaft The range of the sync motor became an issue when the turbine was carrying a 12MW load Operations needed to raise the speed to sync to achieve additional load Could not sync additional load because sync motor was maxed out against the stop collar 	10, 11



No.	Date	Time	ltem	Event	Ref.
200	Annil 25			 Adjustments to the fuel gas linkages were attempted unsuccessfully (April 9) Stop collar was lowered and repined so that the manual speed with no load was 3850 rpm. Linkage settings reversed on April 11 to prior settings Fieldcore/GE requested moving 65 MS shaft collar 	11
290	April 25			 Ran Load Test Measure the S1 (speed control) and V (gas control valve) linkages under load Insufficient load for test 	11
300	April 25			 Decent run on Turbine 5 Got 12.3 MW Central control had to manually bring the turbine back up to speed after each load increase beyond 8 MW 3/8" travel left on sync motor Gas pressure ratio valve is still only open a little more than half stroke but still getting 125 psi of gas pressure at the stop valve 	11
310	Mar 18 – April 14 2019		TG 5 System GE Phase 3 work	At the end of the outage, the turbine was proven to start successfully and hold a load range of 0 – 12 MW Without a larger rain event, SWBNO could not provide a heavier load to test the maximum load of the turbine	10



No.	Date	Time	ltem	Event	Ref.
320	Oct. 1, 2019			Still have not generated significant	10
				load on TG 5	
				Still have the 8 MW	
				restriction	
				Central control still must	
				manually bring up the	
				RPM with the sync motor	
				to maintain anything	
				above 8MW	
330	Oct. 3 to Dec. 11 2019		TG 5 System	TG Ran continuously	
340	Dec 11		TG 5 System	Shutdown for PM	
350	Dec 12		TG 5 System	Started for testing – brought the	
				machine up to speed, but did not	
				load the machine	
				Operator stated that this startup	
				went very smoothly, 'perfect'.	
				Operator was training two other	
				individuals during this startup.	
360	Dec 12		TG 5 System	Shutdown	
370	Dec 14 (Saturday)		Control air	Room	
380	Dec 14		Frequency	#5 Auxiliary had not been powered	
			Converters to #4		
			Aux and #5 Aux		
390	Dec 14		TG 4 System	No pressure because of loss of	
400	Dec 14		TG 5 System	Steam Did not have air pressure initially	
400	Dec 14		TO 5 System	because of the air system issues	
				that led to TG #4 shutting down.	
				Verified air pressure in order to	
				meet permissive for TG 5	
410	Dec 14		TG 5 System	Begin preparing TG 5 for startup to replace power from TG 4	
420	Dec 14	13:35:55	Operator	Operator 1 arrives at main security	8
				gate	
430	Dec 14	13:36:00	Boiler Control	Boiler control room phone call that 8 ends at 13:38:04	
440	Dec 14	13:36:08	TG 5 System	Operator 1 driving to back of 8 plant.	
450	Dec 14	13:36:15	Central Control	Central control on call that ends at 8 13:36:51	
460	Dec 14	13:37:17	Central Control	On a call that ends at 013:38:08. 8	



Final Report						
No.	Date	Time	ltem	Event	Ref.	
470	Dec 14	13:39:05	Central Control	Central Control and Boiler Control	8	
			Boiler Control	oiler Control both on a call that ends at		
				13:39:22.		
480	Dec 14	13:29:22	Central Control	A log or note entry is made.	8	
490	Dec 14	13:40:05	Central Control	Central control on a call (2	8	
				seconds) that ends at 13:40:07		
500	Dec 14	13:40:07	Central Control	A log or note entry is made.	8	
510	Dec 14	13:42:03	Central Control	Central Control and Boiler Control	8	
			Boiler Control	both on a call that ends at		
				13:42:14.		
520	Dec 14	13:42:14	Central Control	A log or note entry is made.	8	
530	Dec 14	13:42:14	Central Control	A log or note entry is made.	8	
540	Dec 14	13:42:54	High Lift Office	Operator 1 enters High Lift Office	8	
				and makes a call from the fixed		
				phone on the wall.		
550	Dec 14	13:43:18	High Lift Office	Operator 1 exits the High Lift	8	
				Office.		
560	Dec 14	13:44:25	High Lift Office	Operator 1 enters the High Lift 8		
				Office to use a cell phone.		
570	Dec 14	13:44:45	High Lift Office	A second operator enters the High 8		
				Lift		
580	Dec 14	13:46:00	High Lift Office	Operator 1 departs High Lift Office 8		
590	Dec 14	13:47:30	TG 5	TG 5 Explosion	8	



DRAFT REPORT

APPENDIX B – CAUSE AND EFFECT TREE







































DRAFT REPORT

APPENDIX C – DATA REQUEST SUMMARY



RFI #	ABSG Item No	Description	Status
1	140	1. Turbine Generator (TG) #5 Control system files and instrument data from the startup(s) of 12-14-19 including the incident.	None
1	110	2. TG #5 Inspection logs.	Received Pre-event Information (1.6)
1	160	3. List of personnel associated with TG #5 operations	Closed
1	191	4. List of personnel involved with TG #5 startup on December 14, 2019	Closed
		5. TG #5 repair and maintenance documents since 2018 restart including but not limited to:	Received Pre-event Information
1	120	a. TG #5 General Electric maintenance and repair documentation for work performed on TG #5 in 2019.	Received Pre-event Information
		b. TG #5 preventative maintenance records from December 2019, prior to incident.	Received Pre-event Information
1	190	6. a. List of General Electric personnel associated with TG #5 repairs	Received Pre-event Information
1	180	b. List of SWBNO Personnel associated with repairs	Closed
1	100	7. TG #5 return to service/startup records (logs, testing reports, etc.)	Received Pre-event Information
1	70	8. List of prior TG #5 issues, especially associated with fuel gas system	Closed
1	150	9. Number of hours TG #5 operated since restart and on what dates.	Open
1	310	10. 1. CCTV and security camera footage	Closed See RFI 4 and 5
2	10	DCS Historical records	Closed
2	20	Activities performed since the incident	Closed





RFI #	ABSG Item No	Description	Status
2	30	Additional drawings - structural	Received 4-Engine & Control Data Turbine 5
2	40	Additional drawings - control system	Received 4-Engine & Control Data Turbine 5 Electrical diagram of relays
2	41	P&IDs	See RFI #4 GE Schematic Piping Diagrams.pdf
2	50	Could the emergency trip system have prevented ignition? (system description p. 1-17)	Closed
2	60	Preliminary investigation reports	Received MGTA 19-626 2020 02 19 Report of Site Visit.pdf
2	80	Inspection logs (T5)	Received Pre-event Information (1.6)
2	90	Startup logs, test reports, etc.	Open Carried forward to RFI #5
2	130	What was the output of the flame detectors?	Open
2	170	List of personnel associated with the maintenance activities on T5 in the last 6 months	Received 1 Pre-Event Information\1.4
2	200	Maintenance procedures	Closed - Have what is avail.
2	210	Witness statements - paper says 12 were in the area	Open
2	220	Control system description - pneumatics (T5)	Closed
2	230	Control system description - hydraulics (T5)	Closed
2	240	Control system description - igniters (T5)	Closed
2	250	The system description provided refers to Figure F to show details of the igniter. We need Figure F.	Open
2	260	Similarities/differences to other TGs? Any other examples out there?	Closed - Only TG of this type.
2	270	Photographs from others - GE	Closed - Have what we can receive
2	280	Photographs from others - SWBNO	Closed - Have what we can receive
2	290	Radio traffic recordings	Closed



RFI #	ABSG Item No	Description	Status
2	320 330	Understand timing for the "no start" case	Closed
2	340	Understand why it is "normal" for the system to not ignite on the first attempt	Open
2	350	Interview Operator 1 for the timing and steps taken before/during the incident. (Any other personnel?)	Closed
2	360 370	Confirm the insect clogging would reduce the air intake to the turbine system.	Closed
2	380	Confirm operational timeline, including purge time between start attempts	Received 1 Pre-Event Information
2	390	What does "removed igniters from combustion chamber" mean in the incident sequence? What was done to the igniters? Tested prior to use?	Closed
2	400	Other than Operator #1	Closed
2	410	What maintenance was done? What records are available?	Received 1 Pre-Event Information
3		1. Interviews	Closed
3		2. full length version of High Lift Camera Video Ops-Skylift Right_20191214_134729 - Ops-Skylift Right.avi	Closed, not available
4		1. P&ID of the control air supply that includes all the air compressors that can supply TG #5 and the equipment supplied at TG #5	Walked Down
4		2. Photographs of the control air supply valves and pressure gauges located on the Mezzanine deck below the turbine	Closed
4		3. Photographs of the control air pressure indicator on the top deck located under the oil and gas pressure gauges on southeast side of Accessory Gear Box (small enclosure) behind panel doors, potentially with a blue label	Closed
4		4. Photographs of the control air toggle switches (located near the floor north of the Leslie valve) and pressure indicator on/near the floor north of the door within the Accessory Gear Box	Closed
4		6.Please confirm that we have received all the available camera footage and if there is additional footage	Closed
5	90	1. Startup checklist form utilized by operators during the startup of Turbine 5	Closed
5	90	2. Startup checklist from the December 14th startup that ended in the Turbine 5 explosion	Open

1



RFI #	ABSG Item No	Description	Status
5	90	3. Startup checklist from the last successful startup of Turbine 5 prior to December 14th.	Closed
5		4. Photographs of the current position of the Leslie Valve indicator disc.	Closed
5		5. Photograph dials and gauges on the Leslie valve (taken straight on reading the gauges)	Closed
6		John H. Carter gas pressure ratio pilot valve bench test report.	Open